



**R66 MAINTENANCE MANUAL
and
INSTRUCTIONS FOR CONTINUED AIRWORTHINESS
RTR 660 VOLUME I**

Production Certificate Number 424WE

Type Certificate Number R00015LA



Robinson Helicopter Company
2901 Airport Drive
Torrance, California 90505-6115
United States of America

Phone: (310) 539-0508
Fax: (310) 539-5198
Web: <https://robinsonheli.com>

OFFICE HOURS

Monday through Friday, 6:00 a.m. to 6:00 p.m., Pacific Time.

CUSTOMER SUPPORT AND SPARES ORDERS

Please visit our website <https://robinsonheli.com/support> for the latest customer support contact information. You can also find a map of our global dealers and service centers that will be able to assist at <https://robinsonheli.com/dealers-and-service-centers>.

PUBLICATIONS

Viewing RHC Maintenance Manuals (MMs) and Illustrated Parts Catalogs (IPCs) online at <https://robinsonheli.com/publications> is recommended to ensure use of current data. Viewing MMs and IPCs offline via paper or digital download requires verification that the data is current. Refer to the online MM or IPC Revision Log for the list of current pages.

SUBSCRIPTION ORDER AND RENEWAL FORMS

Subscription order and renewal forms are located at <https://robinsonheli.com>.

WARRANTY INFORMATION

Helicopter and parts warranty information is located at <https://robinsonheli.com>.

TRADEMARK ACKNOWLEDGMENTS

All trademarks and registered trademarks are the property of their respective owners. Reference to any specific commercial products, process, or service by trade name, trademark, or manufacturer does not necessarily constitute or imply its endorsement.

NOTE

Failure to include the ® or ™ symbols or to capitalize specific brand names within the body of this manual does not constitute a waiver of the trademark rights by the respective owners.

- CherryMAX® is a registered trademark of Cherry Aerospace.
- Heli-Coil® is a registered trademark of Böllhoff Group.
- Loctite®, Alodine®, and BONDERITE® are registered trademarks of Henkel AG & Co. KGaA.
- LPS® is a registered trademark of ITW Pro Brands.
- Molykote® is a registered trademark of DuPont Specialty Products USA, LLC.
- Palnut® is a registered trademark of A. Raymond Tinnerman.
- Scotch-Brite™ is a trademark of 3M Company.
- Teflon™ is a trademark of The Chemours Company FC, LLC.
- Ty-Rap® is a registered trademark of ABB Installation Products.

1-92 Additional Component Maintenance (continued)

A. 12 YEARS (continued)

Part Number	Description	Action
C343-8	Tube	Disassemble and visually inspect exterior and interior. Verify no corrosion.
D211-3	Hydraulic Reservoir Assembly	Perform 12-year inspection per § 5-54, or replace with new or overhaul exchange.
D212-5, -6	Hydraulic Servo Assembly	Perform inspection per § 29-30 Part C.
D918-1	Elastic Cord – Longitudinal (cyclic pivot)	Replace with new.
D918-2	Elastic Cord – Lateral (cyclic pivot)	Replace with new.
D918-3	Elastic Cord – (collective)	Replace with new.
F006-1, -6	Main Rotor Gearbox Assembly	Submit to RHC for 12-year maintenance, or replace with new or overhaul exchange. 12-year maintenance includes seal replacement, o-ring replacement, sealed bearing replacement, rubber mount replacement, R66 SL-11 upgrade (as applicable), and inspection.
F014	Landing Gear Assembly	Perform 12-year inspection per § 5-53, or replace with new.
F018-1	Clutch Assembly (Revision C & prior)	Replace with new or overhaul exchange clutch assembly.
F018-1	Clutch Assembly (Revision D & subsequent)	Submit to RHC for 12-year maintenance, or replace with new or overhaul exchange. 12-year maintenance includes seal replacement, o-ring replacement, and inspection.
F121-3, -5, & -7	Push-Pull Tube Assembly	Disassemble and visually inspect exterior and interior. Verify no corrosion.
F579-1	Engine Air Bellmouth	Replace with new.
F642-6	Engine Shaft Weldment	Replace with new F642-7 weldment.
F650-1, -2	Main Gearbox Mounting Bolts	Visually inspect exterior and interior. Verify no corrosion.
F651-2	Element – Main Gearbox Filter	Replace with new.
F651-3	Seal Kit – Main Gearbox Filter	Replace with new.
F771-1	Filter – Engine Air Intake (foam, standard)	Replace with new.
F771-4	Filter – Starter-Generator (cooling air)	Replace with new.
F771-7	Filter – G918-1 Box Assembly	Replace with new.
F792-1	Dual Tachometer	Perform accuracy check per § 95-23 Part D.
G201-1	Frame, Servo Support	Remove B163-2 rod end. Visually inspect exterior and interior. Verify no corrosion.

1-92 Additional Component Maintenance (continued)

B. 2000 HOURS

Remove the following components when they have accumulated 2000 hours time in service since new or since last overhaul, and perform action indicated:

Part Number	Description	Action
A120-5	Bellcrank – Aft	Replace with new.
A130-48	Spacer (at A462-4 fittings)	Replace with new.
A215-015	O-Ring (rollover valves)	Replace with new.
A462-4	Fitting – Control Cable	Replace with new.
A522-10	Control Cable (FCU fuel cutoff)	Replace with new, or replace inner wire.
A522-11	Control Cable (fuel valve)	Replace with new, or replace inner wire.
A522-14	Control Cable (heater valve)	Replace with new, or replace inner wire.
A729-68	Tube (black, earlier ships; used with G727-1 engine gearbox vent tube)	Replace with new.
A785-36	Hose (engine gearbox vent; earlier ships)	Install KI-258 Firewall Drain Tube Upgrade Kit.
A785-37	Hose (inducer bleed)	Replace with new.
A785-38	Hose (starter-generator)	Replace with new.
A918-1 thru -8, -19, or -20	Elastic Cord Assembly	Replace with new. Dash number is selected during flight test evaluation.
A947-2	Flex Plate Assembly (engine driveline)	Replace with new.
B173-5	V-Belt – Compressor Drive (cabin air conditioning)	Replace with new.
B277-32	Clamp (inducer bleed hose, at engine)	Replace with new.
B297-5 or MS26574-5	AUTOPILOT FCS (5 amp) circuit breaker (Garmin FCS installation only)	Replace with new B297-5 Revision G or subsequent, or MS26574-5 circuit breaker.
C005-4	Main Rotor Hub (C154-1) & Bearing Assembly	Replace with new.
C005-13	Main Rotor Blade and Spindle Assembly	Replace with new or overhaul exchange C005-13 main rotor blade and spindle assembly.
C008-10	Tail Rotor Assembly	Replace with new.
C017-6	Swashplate Assembly	Replace with new or overhaul exchange C017-6 swashplate assembly.
C021-1	Tail Rotor Gearbox Assembly	Replace with new or overhaul exchange tail rotor gearbox assembly.
C031-1	Tail Rotor Pitch Control	Replace with new.
C119-2	Bumper – Tail Rotor	Replace with new.
C258-1	Main Rotor Pitch Link Assembly	Replace with new C258-5 link assembly.

1-92 Additional Component Maintenance (continued)
B. 2000 HOURS (continued)

Part Number	Description	Action
C258-5	Main Rotor Pitch Link Assembly	Replace with new, or perform inspection per § 5-51 and magnetic particle inspect barrel.
C522-10	Control Cable (FCU throttle)	Replace with new.
C522-11	Control Cable (PTG)	Replace with new.
C649-4	Oil Cooler (main rotor gearbox oil)	Replace with new, or overhaul oil cooler.
C947-3	Flex Plate Assembly (tail rotor driveline)	Replace with new.
D082-1	Tube Assembly (tail rotor guard mount)	Magnetic particle inspect or replace with new.
D211-3	Hydraulic Reservoir Assembly	Replace with new or overhaul exchange reservoir assembly.
D212-5	Hydraulic Servo Assembly	Replace with new or overhaul exchange servo assembly.
D212-6	Hydraulic Servo Assembly	Replace with new or overhaul exchange servo assembly.
D224-3 and -4	Tail Rotor Drive Shaft (D196-1) Assembly	Refer to § 4-30. Replace with new D224-4 tail rotor drive shaft assembly, if required.
D333-13	Fitting (PTG)	Replace with new.
D500-2	Hydraulic Pump Assembly	Replace with new or overhaul exchange pump assembly.
D500-3	Main Rotor Gearbox Oil Pump Assembly	Replace with new or overhaul exchange pump assembly.
D918-1	Elastic Cord – Longitudinal (cyclic pivot)	Replace with new.
D918-2	Elastic Cord – Lateral (cyclic pivot)	Replace with new.
D918-3	Elastic Cord – (collective)	Replace with new.
D930-2	Spring – Safety (FCU throttle input)	Replace with new.
F006-1, -6	Main Rotor Gearbox Assembly	Refer to § 4-30. Replace with new or overhaul exchange F006-1 or F006-6 gearbox assembly, as required.
F018-1	Clutch Assembly	Replace with new or overhaul exchange clutch assembly.
F101-4	Rod End, Elastomeric	Replace with new.
F170-1, -2	Fitting (engine gearbox vent)	Replace with new F170-2 fitting.
F173-1	Strut (exhaust weldment support)	Replace with new.
F453-5	Retainer (at firewall seal)	Replace with new.
F579-1	Engine Air Bellmouth	Replace with new.
F597-1	Seal – Firewall	Replace with new.
F642-6, -7	Engine Shaft Weldment	Replace with new F642-7 weldment.
F649-1	Oil Cooler (engine oil)	Replace with new, or overhaul oil cooler.
F651-2	Element – Main Gearbox Filter	Replace with new.

1-92 Additional Component Maintenance (continued)

B. 2000 HOURS (continued)

Part Number	Description	Action
F651-3	Seal Kit – Main Gearbox Filter	Replace with new.
F771-1	Filter – Engine Air Intake (foam, standard)	Replace with new.
F771-4	Filter – Starter-Generator (cooling air)	Replace with new.
F771-7	Filter – G918-1 Box Assembly	Replace with new.
F792-1 or -2	Dual Tachometer	Replace with new.
G732-2	Cap (with C130-62 spacer)	Replace with G732-3 cap.
A880-908 or AN815-8D	Union – Engine Oil Outlet (replaces CV26-77 check valve on helicopter S/N 0222 and prior)	Replace with new.
A880-908 or AN815-8D	Union – Oil Tank Vent (at engine)	Replace with new.
A880-910 or AN815-10D	Union – Engine Oil Inlet	Replace with new.
MS16562-4	Spring Pin (at D333-13 fitting on PTG lever)	Replace with new.
MS29512-10	Packing (left rollover valve)	Replace with new.
NAS1149E0363R	Washer (at A462-4 fittings)	Replace with new.
NAS557-32A	Grommet – Firewall (engine drive shaft weldment)	Replace with new.
NAS6604-67 or G732-4	Bolt (clutch assembly)	Replace with new G732-4 bolt.

5-45 100-Hour / Annual Inspection (continued)

HORIZONTAL CONTROL TUNNEL (Front seats)

Covers:

Inspect condition. Verify marking legibility.

Antenna Wiring & Connectors:

Inspect condition. Verify no loose, chafed, frayed, or broken wires. Verify no damaged connectors. Verify neatness, proper routing and installation, and security.

Cyclic Box Assembly:

Inspect condition. Verify no nicks, scratches, dents, cracks, corrosion, or loose rivets. Verify no distortion or damage on cyclic stop sheet metal assembly. Verify security.

Cyclic Stick Assembly:

Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion. Verify no cracks in welds. If paint has worn thru to metal, touch-up with § 20-75 approved primer. Verify security, proper operating clearance, and smooth actuation. Verify security of removable co-pilot grip and locking pin.

Cyclic Boot:

Inspect condition. Verify proper locking function of boot snaps. Verify no defects, tears, or material deterioration. Verify security.

Cyclic Friction Assembly:

Inspect condition. Inspect link rod end bearings per § 5-33. Verify no excessive flaring at either end of friction spacer. Verify proper installation, security, and operation.

Cyclic Pivot:

Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion. Inspect spherical bearings per § 5-33. Verify proper installation, security, and operating clearance.

Cyclic Torque Tube:

Examine accessible portion with inspection light and mirror. Verify no nicks, scratches, dents, cracks, or corrosion. Verify no cracks around reinforcement blocks on forward end of torque tube. Verify proper installation, security, and operating clearance.

Horizontal Push-Pull Tubes:

Examine accessible portion with inspection light and mirror. Inspect condition per § 5-32. Verify no nicks, scratches, chafing, dents, cracks, or corrosion. Inspect rod end bearings per § 5-33; verify rod ends are centered and stamped nut and jam nut are tight. Check witness holes for proper thread engagement. Verify proper installation, security, and operating clearance.

5-45 100-Hour / Annual Inspection (continued)

HORIZONTAL CONTROL TUNNEL (Front seats; continued)

Collective Stick Assembly:

Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion. Verify no cracks in welds. Verify proper installation, security, and operation of collective micro switches. Verify security, proper operating clearance, and smooth actuation of both flight and throttle controls. Verify over center spring holds twist grip full open or full closed. Verify placard legibility.

Collective Stick Torque Tube:

Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion.

Collective Boot:

Inspect condition. Verify proper locking function of boot snaps. Verify ty-rap is properly installed (loosely securing boot around collective stick). Verify no defects, tears, or material deterioration. Verify security.

Fuel Valve Knob and Guard:

Inspect condition. Verify cable and mounting bezel security. Verify proper adjustment and smooth operation of valve. Verify guard is present.

Collective Friction & Stop Assembly:

Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion in stop assembly. Verify no bending or binding of stop through full control travel, with and without friction applied. Measure collective friction per § 67-22. Verify proper installation and security of collective friction lever and stop assembly.

Autopilot (if installed; Garmin or HeliSAS):

Inspect condition of pitch & roll servos and linkages to cyclic, and wiring; verify security, no obvious damage, & neatness. While observing servo linkages, have second person manipulate flight controls thru full range of travel; verify operating clearance.

Co-Pilot Removable Collective Stick Assembly:

Remove co-pilot collective stick assembly. Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion. Verify no damage to spring pin and safety wire at coupling. Firmly grasp coupling and rotate twist grip in each direction with opposite hand. Verify no free play of coupling or spacer relative to torque tube. Install removable collective stick in helicopter and verify both locking pins engage holes to secure stick. Verify security, proper operating clearance, and smooth actuation of both flight and throttle controls. Verify placard legibility.

Co-Pilot Removable Collective Boot:

Inspect condition. Verify proper locking function of boot snaps. Verify ty-rap is properly installed (loosely securing boot around collective stick). Verify no defects, tears, or material deterioration. Verify security.

5-45 100-Hour / Annual Inspection (continued)

HORIZONTAL CONTROL TUNNEL (Front seats; continued)

Pitot & Static Lines & Drains:

Inspect pitot and static lines for obstructions, cracking, chafing, pinching, or kinking. If internal moisture is evident, remove drain plug from tee fitting on affected line, remove moisture, install drain plug(s), and verify integrity of pitot and static line connections. Verify line security.

Wiring:

Inspect condition. Verify no loose, chafed, or broken wires or terminals. Verify neatness, proper routing and installation, and security.

Fasteners & Torque Stripes:

Inspect condition. Verify proper installation and security of fasteners. Renew deteriorated torque stripes per Figure 5-1.

Antennas:

Inspect condition. Verify no cracks where antennas mount to cowling. Verify security.

Close & Secure:

Verify foreign objects are removed. Verify equipment security. Verify cleanliness of interior and of inspection and access covers and cowlings. Connect ELT (if installed) wiring at connectors and anti-ice switch wiring terminals under cyclic box cover. Connect antenna leads and ground wires (if installed). Install covers and cowlings removed in preceding steps. Verify security. Verify security of removable and adjustable controls. Fasten cyclic, collective, and removable collective boot snaps.

5-45 100-Hour / Annual Inspection (continued)

HORIZONTAL CONTROL TUNNEL (Aft seats)

_____ **Covers:**

Inspect condition. Verify marking legibility.

_____ **Antenna Wiring & Connectors:**

Inspect condition. Verify no loose, chafed, frayed, or broken wires. Verify no damaged connectors. Verify neatness, proper routing and installation, and security.

_____ **Cyclic Yoke:**

Inspect condition. Verify no cracks, corrosion, or fretting. Inspect spherical bearings per § 5-33. Verify proper installation, security, and operating clearance.

_____ **Cyclic Fork:**

Inspect condition. Verify no nicks, scratches, dents, cracks, or corrosion. Inspect rod end bearings per § 5-33. Verify proper installation, security, and operating clearance.

| _____ **Cyclic Torque Tube:**

Examine accessible portion with inspection light and mirror. Verify no nicks, scratches, dents, cracks, or corrosion. Verify no cracks around reinforcement blocks on aft end of torque tube. Verify proper installation, security, and operating clearance.

_____ **Horizontal Push-Pull Tubes:**

Examine accessible portion with inspection light and mirror. Inspect condition per § 5-32. Verify no nicks, scratches, chafing, dents, cracks, or corrosion. Inspect rod end bearings per § 5-33; verify rod ends are centered and stamped nut and jam nut are tight. Check witness holes for proper thread engagement. Verify proper installation, security, and operating clearance.

CHAPTER 22

AUTOPILOT

<i>Section</i>	<i>Title</i>	<i>Page</i>
22-00	Introduction	22.1
22-10	Garmin Flight Control System (FCS)	22.1
22-11	Description	22.1
22-12	Garmin FCS – Servo Assemblies	22.4
22-12-1	Garmin FCS – Pitch Servo Assembly	22.4
22-12-2	Garmin FCS – Roll Servo Assembly	22.6
22-12-3	Garmin FCS – Yaw Servo Assembly (3-Axis Installation only)	22.8
22-12-4	Garmin FCS – Pitch and Roll Servo Output Arm Friction Adjustment	22.10
22-12-5	Garmin FCS – Shear Fuse	22.11
22-12-6	Garmin FCS – Servo Range Verification	22.11
22-13	Garmin FCS – Collective Position Sensor (G356-1 Transducer Assembly)	22.12
22-14	Garmin FCS – GMC 605H Mode Controller	22.14
22-15	Garmin FCS – Cyclic Grip Assembly	22.15
22-16	Garmin FCS – Maintenance and Inspections	22.17
22-16-1	Garmin FCS – Configuration	22.17
22-16-2	Garmin FCS – Calibration	22.23
22-16-3	Garmin FCS – Inspections	22.26
22-17	Garmin FCS – Ground Checks	22.28
22-17-1	Garmin FCS – Configuration Mode Functional Checkout	22.28
22-17-2	Garmin FCS – Normal Mode Functional Checkout	22.31
22-18	Garmin FCS – Troubleshooting	22.43
22-20	HeliSAS (Stability Augmentation System)	22.53
22-21	HeliSAS – Description	22.53
22-22	HeliSAS – (Pitch) Servo Assembly	22.59
22-23	HeliSAS – (Roll) Servo Assembly	22.60
22-24	HeliSAS – Flight Control Computer (FCC)	22.61
22-25	HeliSAS – Control Panel	22.62
22-26	HeliSAS – Cyclic Grip Assembly	22.63
22-27	HeliSAS – Maintenance	22.64

Intentionally Blank

CHAPTER 22

AUTOPILOT

22-00 Introduction

Two different autopilot systems are available as optional equipment on R66 helicopters.

Refer to § 22-10 for Garmin Flight Control System (FCS).

Refer to § 22-20 for HeliSAS (Stability Augmentation System).

22-10 Garmin Flight Control System (FCS)22-11 Description

The Garmin GFC 600H Helicopter Flight Control System (FCS), consists of a GMC 605H Mode Controller, two GFS 83 servos for pitch & roll, an optional third servo for yaw, a GSU 75H ADAHRS (Air Data and Attitude Heading Reference System), GPS from a GTN, and a collective position sensor. Power to the FCS is provided through the AUTOPILOT FCS circuit breaker and avionics master switch.

The GMC 605H Mode Controller, located in the center console, is one means for the pilot to interface with the GFC 600H system. The GMC 605H Mode Controller displays active modes, references, and Crew-Alerting System (CAS) messages. Bezel keys provide a means to engage/disengage the FCS system and individual modes.

The GFS 83 is an electromechanical “smart” servo which activates the flight controls and also performs many FCS processing functions. The GFS 83 servos are installed in parallel with the primary flight controls, resulting in cyclic movement (2-axis), and antitorque pedal movement (3-axis only) directly proportional to movement of the servo. The GFS 83 provides fly-through capabilities, meaning that the pilot can override the system at any time by flying through any control forces which may be present. Upon releasing the controls, the system will return to its commanded references.

The GFS 83 servos installed for pitch and roll are a direct-drive style. This servo provides a fail-passive damping feature which reduces attitude deviation in the event of servo disconnect while the pilot’s hands are not on the controls. In the event of a mechanical jam in the servo, the pilot must apply sufficient force to the affected rotorcraft flight control to break the shear fuse at the output shaft of the servo, removing the servo from the control system and allowing free movement of the flight control. Some residual friction will be felt in the control axis after breaking the shear fuse.

Refer to R66 Pilot’s Operating Handbook (POH) Garmin GFC 600H Supplement for illustration of relative control forces.

For the optional 3-axis installation, a mechanically-clutched GFS 83 servo is installed for yaw. This servo contains a mechanical clutch to engage the motor drive to the servo output.




FIGURE 22-1 GARMIN FLIGHT CONTROL SYSTEM (FCS) – BLOCK DIAGRAM

22-11 Description (continued)

The GFC 600H system uses a minimum of two attitude sources and one air data source. A Garmin GSU 75H ADAHRS provides the primary attitude data and air data. The GMC 605H Mode Controller provides the second attitude source which is used to monitor the primary attitude source.

A Garmin GPS position source provides aiding to AHRS and is required for the ground Speed Hold (GSPD) and hover position hold (HOV), along with GPS navigational data for upper modes.

A position sensor provides collective position to the GFC 600H to improve system performance and aid in determining if the helicopter is on the ground.

Refer to R66 POH Section 9, Garmin GFC 600H Supplement, for operational details.




FIGURE 22-2 GARMIN FCS – PITCH SERVO ASSEMBLY

22-12 Garmin FCS – Servo Assemblies

22-12-1 Garmin FCS – Pitch Servo Assembly

A. Removal

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Refer to Figure 22-2 and IPC Figure 6-1. Remove hardware securing F680-3 cover and F445 collective covers, F640 avionics face, and F444 cyclic cover.

22-12-1 Garmin FCS – Pitch Servo Assembly (continued)**A. Removal (continued)**

3. Remove avionics from lower console. Remove hardware securing avionics trays and remove trays from lower console.
4. Disconnect G323-1 or -2 harness assembly from servo assembly.
5. Position cyclic stick approximately mid-travel, longitudinally. Remove hardware (and C130-64 spacer) securing A336-8 tube's forward rod end to G357-2 servo assembly output arm.
6. While supporting servo, remove hardware and A130-35 spacers securing servo to F359-1 panel. Carefully remove servo from control tunnel.

B. Installation

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Verify A336-8 tube dimension is 4.60 ± 0.03 inches between rod end centers.
3. Position G357-2 servo assembly in control tunnel and install hardware and A130-35 spacers securing servo to F359-1 panel. Standard torque screws per § 20-32 and torque stripe per Figure 5-1. Verify security.
4. Install hardware (and C130-64 spacer) securing A336-8 tube's forward rod end to servo assembly output arm. Standard torque bolt per § 20-32 and torque stripe per Figure 5-1.
5. Perform servo-to-cabin electrical bonding check per § 22-16-3 Part B.
6. Connect G323-1 or -2 harness assembly to servo assembly. Verify harness security.
7. Move flight controls through full travel. Verify no binding or interference.
8. Install hardware securing avionics trays to lower console. Perform rack-to-cabin electrical bonding check per § 22-16-3 Part B.
9. Install avionics in appropriate location, if removed.
10. Refer to Figure 22-2 and IPC Figure 6-1. Install hardware securing F444 cyclic cover, F640 avionics face, and F445 and F680-3 collective covers.
11. If installing a replacement servo, or if servo has had maintenance performed, load software per § 22-16-1 Part C.
12. Perform servo range calibration per § 22-16-2 Part A.




FIGURE 22-3 GARMIN FCS – ROLL SERVO ASSEMBLY

22-12-2 Garmin FCS – Roll Servo Assembly

A. Removal

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Refer to Figure 22-3 and IPC Figures 6-1, 6-11, and 6-13. Remove hardware securing F680-3 cover, F445 collective covers, and F794-1 panel.
3. Hinge front right seat forward. Remove hardware securing G702-14 cover assembly under pilot’s seat and remove cover from helicopter.
4. Disconnect G323-1 or -2 harness assembly from G357-1 roll servo assembly.

22-12-2 Garmin FCS – Roll Servo Assembly (continued)**A. Removal (continued)**

5. Position cyclic stick full forward and apply cyclic friction. Remove hardware (and C130-51 spacer) securing A336-7 tube's rod end to C069-23 or -24 cyclic stick assembly.
6. Refer to Figure 22-3. While supporting servo, remove screws securing G353-2 angle and G353-3 angle assembly and remove servo from under seat.

B. Installation

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel. Position cyclic stick full forward and apply cyclic friction.
2. If not previously accomplished, install hardware (and A130-20 and -35 spacers) securing G353-2 angle and G353-3 angle assembly to G357-1 servo assembly. Standard torque screws per § 20-32 and torque stripe per Figure 5-1.
3. Verify A336-7 tube dimension is 5.44 ± 0.03 inches between rod end centers.
4. If not previously accomplished, install hardware securing A336-7 tube's rod end to servo assembly's output arm. Standard torque hardware per § 20-32 and torque stripe per Figure 5-1.
5. Refer to Figure 22-3. Position servo assembly under pilot's seat, ensure A336-7 tube is thru hole in F293-2 panel and install screws securing G353-2 angle and G353-3 angle assembly to cabin. Verify security.
6. Install hardware (and C130-51 spacer) securing A336-7 push-pull tube's rod end to C069-23 or -24 cyclic stick assembly. Standard torque bolt per § 20-32 and torque stripe per Figure 5-1.
7. Perform servo-to-cabin electrical bonding check per § 22-16-3 Part B.
8. Connect G323-1 or -2 harness assembly to servo assembly. Verify harness security.
9. Move flight controls through full travel. Verify no binding or interference.
10. Refer to Figure 22-3 and IPC Figures 6-1, 6-11, and 6-13. Install screws securing G702-14 cover assembly under pilot's seat. Install F445, F680-3 collective covers, and F794-1 panel. Verify security.
11. If installing a replacement servo, or if servo has had maintenance performed, load software per § 22-16-1 Part C.
12. Perform servo range calibration per § 22-16-2 Part A.




FIGURE 22-4 GARMIN FCS – YAW SERVO ASSEMBLY (3-AXIS INSTALLATION ONLY)

22-12-3 Garmin FCS – Yaw Servo Assembly (3-Axis Installation Only)

A. Removal

NOTE

G357-3 yaw servo assembly is required in the Garmin FCS 3-axis system. Removing yaw servo does not reconfigure the 3-axis to a 2-axis system.

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Refer to Figure 22-4. Remove pilot side carpet and scuff plate from floor per § 25-30. Remove screws securing A412-4 cover and C795-1 cover.
3. Loosen B277-12 clamp and remove (2) MS21919CHW18 clamps securing A785-39 hose. Gently move hose clear from under G357-3 servo assembly.

22-12-3 Garmin FCS – Yaw Servo Assembly (3-Axis Installation Only; continued)**A. Removal (continued)**

4. Remove hardware securing C343-11 push-pull tube assembly and G353-5 tube's rod end to D755-4 pedal assembly.
5. Remove hardware securing F349-1 support assembly to lower console. Lift and temporarily secure support assembly to allow for servo assembly removal.
6. Disconnect G323-2 harness assembly from servo assembly.
7. While supporting servo assembly, remove screws and D210-3 nuts securing servo to floor and remove servo thru inspection hole in chin.

B. Installation

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Verify G353-5 tube dimension is 5.10 ± 0.03 inches between rod end centers.
3. If not previously accomplished, install hardware (and C130-15 spacer) securing G353-5 push-pull tube's rod end to G357-3 yaw servo assembly's output arm.
4. Insert servo assembly thru inspection hole in chin and position in floor. Install (2) MS27039C1-07 screws, (2) MS27039C1-08 screws, and (4) D210-3 nuts securing G353-4 plate and servo assembly to floor. Standard torque screws per § 20-32.
5. Position F349-1 support assembly in lower console. Install hardware securing support assembly to lower console.
6. Install hardware securing G353-5 tube's rod end and C343-11 push-pull tube assembly to D755-4 pedal assembly. Standard torque bolt per § 20-32. Install stamped nut, standard torque per § 20-32, and torque stripe per Figure 5-1.
7. Install A785-39 hose on G400-1 tee assembly and tighten B277-12 clamp. Install (2) MS21919CHW18 clamps securing hose to chin.
8. Perform servo-to-cabin electrical bonding check per § 22-16-3 Part B.
9. Connect G323-2 harness assembly to servo assembly. Verify harness security.
10. Move flight controls through full travel. Verify no binding or interference.
11. Refer to Figure 22-4. Install screws securing A412-4 cover and C795-1 cover. Install carpet and scuff plate per § 25-30.
12. If installing a replacement servo, or if servo has had maintenance performed, load software per § 22-16-1 Part C.
13. Perform servo range calibration per § 22-16-2 Part A.

22-12-4 Garmin FCS – Pitch and Roll Servo Output Arm Friction Adjustment

NOTE

Output arm friction adjustment is required after any disassembly of servo output arm, replacement of suspect or worn shear fuse, or when directed by § 22-16-3 scheduled inspections.

1. Remove pitch or roll servo assembly per §§ 22-12-1 or 22-12-2, as required.
2. Remove (2) 211-A0020-26 screws securing 117-01067-05 shear fuse to output hub and output arm. Verify shear fuse is not cracked or damaged.

NOTE

To prevent shaft rotation, use a back-up wrench on output hub when applying torque to output arm or D210-8 nut.

3. Set torque wrench to 60 in.-lb during initial setup, or set torque wrench to recorded value determined in step 8.
4. Using a torque-indicating wrench with an attached 9/16 crowfoot wrench, measure and record breakaway torque required to begin rotating output arm clockwise.
5. Loosen D210-8 nut to realign output arm, then retorque nut using same torque wrench setting used for previous step.
6. Using a torque-indicating wrench, measure and record breakaway torque required to begin rotating output arm counterclockwise.
7. Calculate average breakaway torque required to rotate arm in both directions:

$$\frac{(\textit{clockwise breakaway torque} + \textit{counterclockwise breakaway torque})}{2} = \underline{\hspace{2cm}} \text{ avge in.-lb}$$

8. If average breakaway torque is:
 - a. Between 120–150 in.-lb, record final torque wrench setting used and proceed to step 9.
 - b. Below 120–150 in.-lb, incrementally increase torque wrench setting and temporarily record new torque value, then repeat steps 3 thru 8 using new torque wrench setting.
 - c. Above 120–150 in.-lb, incrementally decrease torque wrench setting and temporarily record new torque value, then repeat steps 3 thru 8 using new torque wrench setting.
9. Loosen D210-8 nut to realign output arm to output hub.
10. Install (2) 211-A0020-26 screws securing 117-01067-05 shear fuse to output arm and hub.
11. Using a backup wrench on output hub, torque D210-8 nut using final torque wrench setting required to obtain 120–150 in.-lb average breakaway torque.

22-12-5 Garmin FCS – Shear Fuse**CAUTION**

If shear fuse was broken by a pilot overcoming a mechanical jam in the servo, the servo must be replaced prior to the next flight.

A. Removal

1. Remove pitch or roll servo assembly per §§ 22-12-1 or 22-12-2, as required
2. Remove (2) 211-A0020-26 screws securing 117-01067-05 shear fuse to output hub and output arm. Discard shear fuse if cracked or deformed.

B. Installation

1. Align slots in output hub and output arm.
2. Install (2) 211-A0020-26 screws securing 117-01067-05 shear fuse to output hub and output arm.
3. As required, reinstall pitch or roll servo assembly per §§ 22-12-1 or 22-12-2 and perform servo range calibration per § 22-16-2 Part A.

22-12-6 Garmin FCS – Servo Range Verification

1. Using avionics switch, power on GMC 605H mode controller in configuration mode per § 22-16-1.
2. Refer to Figure 22-7. Navigate to GFC menu, SERVOS page.
3. Use the NOSE UP/DN thumbwheel to highlight:
 - a. PITCH→STAT, then move cyclic stick full forward & aft and verify GMC displays POSTN 0% thru 100%.
 - b. ROLL→STAT, then move cyclic stick full left & right and verify GMC displays POSTN 0% thru 100%.
 - c. YAW→STAT (3-axis installation only), then move pedals full left & right and verify GMC displays POSTN 0% thru 100%.
4. If the GMC 605H displays OOR before reaching flight control stop, perform servo range calibration per § 22-16-2 Part A.
5. Using avionics switch, power off GMC 605H to exit configuration mode.




FIGURE 22-6 GARMIN FCS – G356-1 TRANSDUCER ASSEMBLY

22-13 Garmin FCS – Collective Position Sensor (G356-1 Transducer Assembly)

A. Removal

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Refer to IPC Figures 6-1 & 6-3. Remove co-pilot collective stick. Remove F680-1 cover and F461 cover.
3. Hinge front left seat forward and raise collective.
4. Refer to Figure 22-6. Cut and discard ty-raps as required and disconnect G356-1 transducer assembly harness from G323-1 or -2 harness assembly.

CAUTION

Only extend transducer cable enough to install on collective stick; overextending cable will damage transducer. Transducer cable must retract slowly; allowing cable to freely retract can damage transducer.

22-13 Garmin FCS – Collective Position Sensor (G356-1 Transducer Assembly; continued)**A. Removal (continued)**

5. Temporarily secure transducer's cable to collective stick using a strip of tape. Remove fastener securing B260-4 terminal and outboard AN742-3 clamp to collective stick assembly. Grasp cable, remove tape, allow cable to retract slowly into transducer housing.
6. Remove hardware securing transducer to seat support and remove transducer.

B. Installation

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Hinge front seat forward and raise collective.
3. Refer to Figure 22-6. Position G356-1 transducer assembly on seat assembly and install hardware (do not overtighten) securing transducer. Verify security.

CAUTION

Only extend transducer cable enough to install on collective stick; overextending cable will damage transducer. Transducer cable must retract slowly; allowing cable to freely retract can damage transducer.

4. Route transducer cable around collective stick assembly and temporarily secure transducer's cable to collective using a strip of tape. Install hardware securing B260-4 terminal and outboard AN742-3 clamp to collective, verify security and remove temporary tape.

NOTE

If C522-10 (throttle) control cable moved from original position, perform FCU throttle control rigging per § 76-11.

5. Connect transducer assembly at electrical connector and lock connectors using MS3367-4-9 ty-rap. Install MS3367-4-9 ty-raps securing wiring to seat, as required. Cinch ty-raps until snug without over-tightening and trim tips flush with heads.
6. Refer to IPC Figures 6-1 & 6-3. Install hardware securing F680-1 cover and F461-1 Cover. Verify security.
7. Install F758-2 or -4 collective stick assembly, if required.
8. Perform collective position sensor calibration per § 22-16-2 Part B.

C. Schematic

Refer to Figure 98-8A for Garmin Flight Control System (FCS) electrical system schematic.

22-14 Garmin FCS – GMC 605H Mode Controller**A. Removal**

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Using a 3/32 inch hex drive tool loosen radio key locking GMC 605H mode controller to avionics tray.
3. Carefully unplug/remove mode controller from avionics tray.

B. Installation

1. Turn battery & avionics switches off and pull open AUTOPILOT FCS (5 amp) circuit breaker on circuit breaker panel.
2. Refer to Figure 22-2. Carefully plug/install GMC 605H mode controller into appropriate location in avionics tray.
3. Tighten radio key securing mode controller to avionics tray.
4. If installing a replacement mode controller, or if controller has had maintenance performed, load software per § 22-16-1 Part C and verify configuration settings per § 22-16-1 Part B.
5. Refer to Table 22-1. Perform required post-installation calibrations.
6. Perform FCS Preflight Test (PFT) per § 22-17-2 Part A.

22-15 Garmin FCS – Cyclic Grip Assembly**A. Grip Angle Adjustment**

1. Loosen cap screws securing pilot's cyclic grip, block assembly, and bar to grip weldment.
2. Rotate grip about weldment to desired angle. Special torque cap screws to 40 in.-lb.

B. Removal and Installation

To access grip switches:

1. Remove MS24693-S1 screws securing C214-28 plate to D379-1 grip. Remove switch nuts and lockwashers to free switches from plate.
2. Install switch lockwashers (new) and nuts and tighten switches to plate; verify switch security. Install screws securing plate to grip.
3. Turn battery switch on and verify cyclic grip switches function properly.

C. Schematic

Refer to Figure 98-8A for Garmin Flight Control System (FCS) electrical system schematic.




FIGURE 22-7 GARMIN FCS – CONFIGURATION MODE MAP

22-16 Garmin FCS – Maintenance and Inspections

22-16-1 Garmin FCS – Configuration

Modern avionics software is complex and subject to rigorous testing by RHC to assure proper function and integration in the aircraft. Only specified software versions and software configurations have been FAA-approved for installation in Robinson helicopters. Software updates should not be attempted without a thorough understanding of approval status and compatibility. Technical support from either RHC or the avionics manufacturer will likely be required. In some cases, updating software for one item of avionics may require additional avionics to be updated to assure compatibility.

As long as RHC-installed equipment is functioning properly, there is no continuing airworthiness requirement to check or update software levels in Robinson helicopters; RHC will issue an SB (or FAA will issue an AD) for any mandatory updates.

Refer to <https://robinsonheli.com> > Customer Support > Avionics Support > Avionics Software page for approved software configurations.

A. Configuration Mode

Configuration mode provides the means to load software, troubleshoot installation issues, set airframe specific configuration settings and perform required calibration procedures for the system.

1. Turn off avionics switch or pull open AUTOPILOT FCS (5 amp) circuit breaker to power off GMC 605H mode controller.
2. Press and hold the LVL key on the GMC 605H and turn avionics switch on or push in AUTOPILOT FCS (5 amp) circuit breaker to power on the GMC 605H.
3. Release the LVL key when the splash screen is displayed.
4. Press the NAV key to continue to configuration mode.
5. Use the IAS and VS keys on the GMC 605H to move the cursor to the left or right, respectively. The VS key is also used to accept the desired selections.
6. Use the NOSE UP/DN thumbwheel to scroll up and down thru the menu and page selections. The wheel is also used for configuration acknowledgment.
7. To exit Configuration mode, power off the GMC 605H.

22-16-1 Garmin FCS – Configuration (continued)

B. Configuration Settings

1. Power on the GMC 605H mode controller in configuration mode per § 22-16-1.
2. Refer to Figure 22-7. Navigate to SYS menu, INSTALL group, and set/verify each value below:

SYS menu					
<u>INSTALL group</u>					
PTRM	=	NO	VNAV	=	NO
Yaw Damper	=	YES (3-axis) NO (2-axis)	COL SNSR	=	POT
GI 285	=	NO	CBN PRSSR	=	NONE
HSI/DG	=	GDU	EIS	=	NONE
Flt Dir	=	NO	RAD ALT	=	NO
GPS ROLSTR	=	YES	YTRM	=	NO
GPS Dev	=	ANGULR	VDI	=	YES

3. Refer to Figure 22-7. Navigate to GMC DSP menu and set/verify the values for each group below:

GMC DSP menu	
<u>BACKLIGHT Page</u>	
SOURCE = PHOTOCELL	
TRANSITION = 25	
<u>LIGHTBUS DISP Page</u>	<u>LIGHTBUS KEYS Page</u>
X1:0 = Y1:1	X1:0 = Y1:1
X2:19 = Y2:10	X2:19 = Y2:10
X3:20 = Y3:15	X3:20 = Y3:15
X4:100 = Y4:30	X4:100 = Y4:30
<u>PHOTOCELL DISP Page</u>	<u>PHOTOCELL KEYS Page</u>
X1:0 = Y1:1	X1:0 = Y1:1
X2:19 = Y2:10	X2:19 = Y2:10
X3:20 = Y3:15	X3:20 = Y3:15
X4:100 = Y4:30	X4:100 = Y4:30
<u>CONTRAST Page</u>	
OFFSET = 0	

22-16-1 Garmin FCS – Configuration (continued)

B. Configuration Settings (continued)

4. Refer to Figure 22-7. Navigate to GFC menu, GPS OFFSET group, and set/verify each value below:

GFC menu	
<u>GPS OFFSET group</u>	
HSDB	= ANT 2 (connected GTN in T/C bay1) = ANT 3 (connected GTN in T/C bay3)
RS232 4	= ANT 2 (connected GPS in T/C bay1) = NONE (GPS not in T/C bay1)
RS232 5	= ANT 3 (connected GPS in T/C bay3) = NONE (GPS not in T/C bay3)

5. Refer to Figure 22-7. Navigate to TEST menu, AUDIO group, and set/verify each value below:

TEST menu	
<u>AUDIO page - AP DISCONNECT TONE</u>	
VOLUME	= 0

6. Power off the GMC 605H to exit configuration mode.

22-16-1 Garmin FCS – Configuration (continued)**C. GFC 600H System Software Loading**

1. Contact RHC Technical Support to request GFC 600H system software and downloading instructions.
2. Run the software image executable and load the software to a blank USB flash drive.
3. Verify that there is no electrical power to GFC 600H system by pulling the AUTOPILOT FCS (5 amp) circuit breaker.
4. Connect the USB flash drive to the GMC 605H mode controller using a USB adapter cable (Garmin P/N 320-00726-01).
5. Power on the GMC 605H in configuration mode per § 22-16-1.
6. Refer to Figure 22-7. Navigate to SYS menu, then SW UPLOAD page.
7. Use the NOSE UP/DN thumbwheel to highlight SW Upload and press the VS key to initialize the software upload.
8. Press the NAV key to load all software components, do not select individual components. Press the NAV key to initiate the software load.

NOTE

When the software upload process is complete, the GMC 605H will restart in Configuration mode and “SOFTWARE UPLOAD SUCCESSFUL” will be displayed. If any errors occur during the upload, view and record the software parts that did not load successfully.

9. Select continue. The GMC 605H will load additional software regions and reboot to the start-up screen. Do not remove power. Verify loader card version displayed on GMC 605H splash screen is correct per R66 Pilot’s Operating Handbook (POH) Garmin GFC 600H Supplement Section 1.
10. Power on the GMC 605H in configuration mode per § 22-16-1.
11. Refer to Figure 22-7. Navigate to PROD menu and verify software version on each page matches those listed in the appropriate helicopter delivery range at: <https://robinsonheli.com> > Customer Support > Avionics Support > Avionics Software and Approximate Helicopter Delivery Dates.
12. Power off the GMC 605H to exit configuration mode.

22-16-1 Garmin FCS – Configuration (continued)**D. Datalogs and Assert Logs****NOTE**

Datalogs and assert logs may be downloaded and used to aid in troubleshooting.

1. Connect a USB flash drive to the GMC 605H mode controller using a USB adapter cable (Garmin P/N 320-00726-01).
2. Power on the GMC 605H in configuration mode per § 22-16-1.
3. Refer to Figure 22-7. Navigate to SYS menu then ASSERTS page or DATALOGS page, as required.
4. Select DOWNLOAD ASSERTS or DOWNLOAD, as applicable.
5. Follow instructions displayed on the GMC 605H to complete the download.
6. Power off the GMC 605H to exit configuration mode.

Conditions that may require post-installation calibration	GMC 605H Pitch/Roll Calibration	GSU 75H Pitch/Roll Calibration	Magnetic Interference Test	GMC 605H & GSU 75H Magnetometer Calibration	GSU 75H / GMU 44B Heading Offset Calibration
GMC 605H was removed (original unit) and the avionics tray was NOT removed and/or loosened.	No				
GMC 605H was removed (original unit) and the avionics tray WAS removed and/or loosened.	Yes	No	No	Yes	Yes
GMC 605H was replaced (new unit), repaired, or exchanged.	Yes	Yes	Yes	Yes	Yes
GMC 605H configuration module was replaced.	Yes	No	No	Yes	Yes
GMU 44B was removed (original unit) and/or replaced (new unit), or the area near the GMU 44B location was degaussed.	No	No	Yes	Yes	Yes
GSU 75H was removed (original unit) and the avionics tray was NOT removed and/or loosened.	No				
GSU 75H was removed (original unit) and the avionics tray WAS removed and/or loosened.	No	Yes	No	Yes	Yes
GSU 75H was replaced (new unit), repaired, or exchanged.	No	Yes	No	Yes	Yes
GSU 75H configuration module was replaced.	No	Yes	Yes	Yes	Yes

TABLE 22-1 GARMIN FCS – POST-INSTALLATION CALIBRATIONS

22-16-2 Garmin FCS – Calibration**NOTE**

All components and flight controls must be installed and properly torqued before performing any calibration procedures.

A. Servo Range Calibration

1. Apply external power to helicopter.

CAUTION

Do not use excessive force when moving flight controls. The GFS 83 servos create resistance in flight controls, abrupt movement may damage the shear fuse.

2. Pressurize hydraulics per § 12-34 steps 1 thru 3. Move flight controls thru full travel to ensure there is no interference or binding.
3. Power on the GMC 605H mode controller in configuration mode per § 22-16-1.
4. Refer to Figure 22-7. Navigate to GFC menu, RANGE CAL group, then select appropriate PITCH/ROLL/YAW page.
5. Use NOSE UP/DN thumbwheel to highlight SAVE STRAP and press the VS key.
6. Wait at least 10 seconds before continuing.
7. Use NOSE UP/DN thumbwheel to highlight START, press the VS key to start, and follow the on-screen instructions. GMC 605H will display CALIBRATION IN PROGRESS.
8. Move cyclic stick full forward and aft for pitch calibration, or left and right for roll calibration, or move pedals from stop to stop for yaw calibration. Select STOP when complete.
9. Verify GMC 605H reports that the range calibration was completed.
10. Perform steps 4 thru 9 for each required servo.

CAUTION

Do not remove FCS power immediately after performing servo range calibration. Wait a minimum of 30 seconds before removing power to prevent servos from becoming inoperable.

11. Power off the GMC 605H to exit configuration mode.
12. Disconnect hydraulic pump per § 12-34.
13. Remove external power from helicopter.

22-16-2 Garmin FCS – Calibration (continued)**B. Collective Position Sensor (G356-1 Transducer) Calibration**

1. Apply external power to helicopter.
2. Power on the GMC 605H mode controller in configuration mode per § 22-16-1.
3. Refer to Figure 22-7. Navigate to GFC menu, COLL SNSR page.
4. Use the NOSE UP/DN thumbwheel to highlight START under BEGIN CALIBRATION and press the VS key.
5. Move collective stick full up and full down per calibration instructions on the GMC 605H display.
6. Press the VS key to save the calibration.
7. After the GMC 605H reports successful calibration, move collective stick full up and verify the GMC 605H displays COLL: 100%, then move collective stick full down and verify the GMC 605H displays COLL: 0%.

NOTE

If at collective full down the GMC 605H displays "N/A", contact RHC Technical Support.

8. Power off the GMC 605H to exit configuration mode.

C. Pitch/Roll Offset Calibration

1. Ensure aircraft is on level ground.
2. Power on GMC 605H mode controller into configuration mode per § 22-16-1 Part A.
3. Refer to Figure 22-7. Navigate to GFC menu, CALIBRATE group, then P/R page.
4. Press VS key to highlight 1/9 (page), then use NOSE UP/DN thumbwheel to view pages 2 thru 8 and perform each action as required.
5. Scroll to 9/9 (page), then use the thumbwheel and VS key to START TEST.
6. When complete, use NOSE UP/DN thumbwheel to highlight QUIT, then press the VS key to quit.

22-16-2 Garmin FCS – Calibration (continued)**D. Magnetometer Calibration****NOTE**

Garmin FCS magnetometer calibration requires simultaneous GMU 44 or GMU 44B magnetometer calibration; refer to § 95-71 Part F Magnetometer Calibration.

NOTE

Perform this procedure during flight check.

1. If not previously accomplished, perform Pitch/Roll Offset Calibration per § 22-16-2 Part C.
2. Ensure aircraft is positioned on a compass rose heading 360° (magnetic north), or select a magnetically clean location and use a calibrated sight compass.
3. Power on GMC 605H mode controller in configuration mode per § 22-16-1 Part A.
4. Refer to Figure 22-7. Navigate to GFC menu→CALIBRATE group→MAG group, then highlight 1/11 (page).
5. Use the NOSE UP/DN thumbwheel to view each page and verify all pre-calibration steps are completed.
6. Press VS key to indicate START TEST.
7. Scroll down one notch to highlight START TEST and press VS key to start.
8. With appropriately rated person at controls, start helicopter. Have pilot hover→turn 30°→land helicopter as required by GMC 605H mode controller's on-screen instructions; repeat until GMC 605H indicates that calibration is complete.
9. Press VS key to complete calibration when indicated.
10. Have pilot complete flight check if required, or land and shutdown helicopter.

22-16-3 Garmin FCS – Inspections

A. Scheduled Inspections

INSPECTION	PROCEDURE	INTERVAL
Visual	Visually inspect all servos, mode controller, collective sensor, tubes & rod ends, and attached LRUs for security. Inspect visible wiring; verify security and no damage. Verify shear fuses on pitch and roll servos are intact with no signs of wear. Gently pull collective sensor cable slightly and allow to retract slowly to verify operation.	Every 100-hour/annual inspection.
AHRS magnetic field model update	Contact Garmin for new magnetic field model.	Every 5 years.
Electrical bonding	Disconnect battery per § 96-10. Disconnect G323-1 or -2 harness from component to be tested. Using milliohm meter, verify: <ul style="list-style-type: none"> • GMC-to-avionics tray is < 5.0 mOHM, • Avionics tray-to-cabin ground stud is < 5.0 mOHM, or • Servo-to-cabin ground stud is < 2.5 mOHM. Repair electrical bonding as required. Connect G323-1 or -2 harness. Connect battery per § 96-10.	Every 600 flight hours or 5 years, whichever occurs first.
Pitot-static system	Perform pitot-static system checks per § 95-10.	Every 2 years.
Servo arm friction verification	Perform servo arm friction adjustment per § 22-12-4 to verify friction.	Every 600 flight hours or 2 years, whichever occurs first.

B. Special Inspections

INSPECTION	PROCEDURE	INTERVAL
Lightning strike	Perform visual inspection. Perform electrical bonding inspection. Inspect equipment for signs of arcing. Inspect OAT probe for damage. Perform GMC 605H and GSU 75H magnetometer calibration.	After suspected lightning strike.
Electrical bonding	Disconnect battery per § 96-10. Disconnect G323-1 or -2 harness from component to be tested. Using milliohm meter, verify: <ul style="list-style-type: none"> • GMC-to-avionics tray is < 5.0 mOHM, • Avionics tray-to-cabin ground stud is < 5.0 mOHM, or • Servo-to-cabin ground stud is < 2.5 mOHM. Repair electrical bonding as required. Connect G323-1 or -2 harness. Connect battery per § 96-10.	After component was removed or replaced.
Hard landing	Perform visual inspection per Part A.	After hard landing.
Display or status LED inoperative	Display or FCS status LED are inoperative, remove and install new GMC 605H per § 22-14.	On condition.

Intentionally Blank

22-17 Garmin FCS – Ground Checks

22-17-1 Garmin FCS – Configuration Mode Functional Checkout

CAUTION

Do not pressurize hydraulic system while any hydraulic system component is disconnected or removed.

A. Servo Directionality Verification

1. Apply external power to helicopter.
2. Pressurize hydraulics per § 12-34 steps 1 thru 3.
3. Rotate cyclic friction knob full off. Move flight controls thru full travel to ensure there is no interference or binding.
4. Power on the GMC 605H mode controller in configuration mode per § 22-16-1.
5. Wait for GDU attitude display to align fully.
6. Position collective stick full down and apply friction.
7. Refer to Figure 22-7. Navigate to TEST menu, SERVO group.
8. Press the VS key to indicate START TEST, scroll up one notch to highlight START TEST, then press the VS key to begin.
9. Verify each trim switch direction annunciates properly on the GMC 605H and helicopter controls move in the correct direction. Press FTR or FCS OFF switch between directions to stop all motion.

Trim Direction	Annunciation	Control Movement
Cyclic – TRIM ADJUST: Right	ROLL: RIGHT	Cyclic Right
Cyclic – TRIM ADJUST: Left	ROLL: LEFT	Cyclic Left
Cyclic – TRIM ADJUST: Up	PITCH: DOWN	Cyclic Forward
Cyclic – TRIM ADJUST: Down	PITCH: UP	Cyclic Aft
Yaw – YAW TRIM: Left	YAW: LEFT	Left Pedal Forward
Yaw – YAW TRIM: Right	YAW: RIGHT	Right Pedal Forward

10. When all directions and switches have been verified, press the VS key on the GMC 605H, then use the NOSE UP/DN thumbwheel to highlight END TEST and press the VS key.
11. Power off the GMC 605H to exit configuration mode.
12. Disconnect hydraulic pump per § 12-34.
13. Remove external power from helicopter.

22-17-1 Garmin FCS – Configuration Mode Functional Checkout (continued)**B. Servo Wiring Verification**

1. Apply external power to helicopter.
2. Power on the GMC 605H mode controller in configuration mode per § 22-16-1.
3. Refer to Figure 22-7. Navigate to GFC menu, SERVOS group.
4. Select PITCH MON1 page and verify the following:
 - a. The AP DISC status is a checkmark.
 - b. When holding the pilot grip FCS OFF switch, the AP DISC status changes to an "X", and when released the status returns to a checkmark.
 - c. When holding the copilot grip FCS OFF switch, the AP DISC status changes to an "X", and when released the status returns to a checkmark.
5. Repeat step 2 for ROLL MON1 and YAW MON1 (3-axis installation only).
6. Select the PITCH MON2 page and verify the following:
 - a. The FTR status is an "X".
 - b. When holding the pilot grip FTR switch, the FTR status changes to a checkmark, and when released the status returns to an "X".
 - c. When holding the copilot FTR switch, the FTR status changes to a checkmark, and when released the status returns to an "X".
7. Repeat step 4 for ROLL MON2 and YAW MON2 (3-axis installation only).
8. Power off the GMC 605H to exit configuration mode.
9. Remove external power from helicopter.

22-17-1 Garmin FCS – Configuration Mode Functional Checkout (continued)

C. GMC 605H Discrete Wiring Verification

1. Apply external power to helicopter.
2. Power on GMC 605H mode controller in configuration mode per § 22-16-1.
3. Refer to Figure 22-7. Navigate to I/O menu, DISCRETE group, then IN page.
4. Press VS key to highlight page number, then use NOSE UP/DN thumbwheel to scroll thru pages to locate each discrete channel (CH).
5. Scroll to page containing (CH 11) AP DISCONNECT function. Press and release pilot, then copilot grip FCS OFF switches while observing GMC display; verify "ACTV" toggles from "Y" to "N" while pressing each FCS OFF switch.
6. Scroll to page containing each of the following channels/functions and verify each function toggles from "N" to "Y" while pressing associated switch:

I/O CH	Switch	Function Name
3	Pilot/copilot grip FTR	PILOT FTR CYCLIC
24	Pilot/copilot grip LVL	LVL ENGAGE 1
4	YAW TRIM left	YAW TRIM LEFT
10	YAW TRIM right	YAW TRIM RIGHT
5	Pilot grip TRIM ADJUST down	PILOT P TRIM UP
6	Pilot grip TRIM ADJUST up	PILOT P TRIM DN
12	Pilot grip TRIM ADJUST left	PILOT R TRIM LEFT
13	Pilot grip TRIM ADJUST right	PILOT R TRIM RGHT

7. 3-axis systems only: Scroll to page containing (CH 16) YD AUTO ENGAGE function. Toggle FCS YAW switch to ENABLE and verify "ACTV" indicates "Y". Toggle FCS YAW switch to DISABLE and verify "ACTV" indicates "N".
8. Power off GMC 605H to exit configuration mode.
9. Remove external power from helicopter.

D. Audio Test

1. Apply external power to helicopter.
2. Power on GMC 605H mode controller in configuration mode per § 22-16-1.
3. Refer to Figure 22-7. Navigate to TEST menu, AUDIO group.
4. Press VS key to select PLAY and verify autopilot disconnect audio tone is playing in headset.
5. Use NOSE UP/DN thumbwheel to highlight STOP, then press VS key to stop.
6. Power off GMC 605H to exit configuration mode.
7. Remove external power from helicopter.

22-17-2 Garmin FCS – Normal Mode Functional Checkout**A. FCS Preflight Test**

1. Turn battery and avionics switches on.
2. Verify loader card version displayed on GMC 605H mode controller splash screen is correct per R66 Pilot's Operating Handbook (POH) Garmin GFC 600H Supplement Section 1.
3. Press the NAV key to continue into normal mode.
4. Verify the following annunciations and displays:
 - a. "PFT" is displayed on the GMC 605H in green text.
 - b. "PFT" is displayed on the PFD in inverse video white.
5. Verify the following sequence of events during PFT:
 - a. The yellow LEDs are illuminated momentarily, followed by the red LEDs being illuminated momentarily next to the FCS key on the GMC 605H.
 - b. "FCS TEST OK" is played through the headsets.
6. Verify the following annunciations and displays after PFT completion:
 - a. "PFT" is not displayed on the GMC 605H or PFD.
 - b. "MANIFEST" is not displayed on the GMC 605H.
 - c. "PFT FAIL" is not displayed on the GMC 605H or PFD.
 - d. "FCS FAIL" is not displayed on the GMC 605H or PFD.



NOTE

If GPS is not available, a persistent "PFT" may appear. Refer to § 22-18 for troubleshooting.



22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

B. Servo Engagement/Disengagement

1. Apply external power to helicopter.
2. Turn battery and avionics switches on and verify PFT passes per Part A.
3. Press the FCS key on the GMC 605H mode controller. Verify the LED is illuminated green and the following annunciators and displays:



If GPS is valid




If GPS is not valid

5. Disengage the system by pressing the FCS key on the GMC 605H.
6. Verify the following (“Y” will only be displayed in 3-axis installation):
 - a. “FCS” status indication light flashes yellow.
 - b. A two-tone aural (high/low) is played through the headsets.
 - c. “R”, “Y”, and “P” annunciators flash yellow until removed on the GDU .
 - d. After 10 seconds, all FCS annunciators should be removed from the PFD and GMC 605H.
7. Press and hold the pilot grip FTR switch to re-engage the system.
8. Verify the following (“Y” will only be displayed in 3-axis installation):
 - a. “R”, “Y”, “P”, and “ATT” are displayed on the GMC 605H.
 - b. “R”, “Y”, and “P” are displayed on the top of the PFD in green text.
9. Press and hold the pilot grip FCS OFF switch to disengage the system.
10. Verify the following (“Y” will only be displayed in 3-axis installation):
 - a. “FCS” status indication light flashes yellow.
 - b. A two-tone aural (high/low) is played through the headsets.
 - c. “R”, “Y”, and “P” annunciators flash yellow until removed on the GDU.
11. Repeat steps 7 through 10 for copilot grip controls, if installed.
12. Turn battery and avionics switches off.
13. Remove external power from helicopter.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

C. GFC 600H Mode Operation Tests

1. Apply external power to helicopter.
2. Turn battery and avionics switches on and verify PFT passes per Part A.
3. Press the LVL key on the GMC 605H.
4. Verify the following (“Y” will only be displayed in 3-axis installation):




5. Press the pilot grip TRIM ADJUST up (nose down) with LVL | LVL active.
6. Verify LVL is no longer the active mode for P and R.

NOTE

If the GFC 600H system is receiving valid GPS, the GMC 605H mode controller will engage HOV mode and display GSPD | GSPD in the pitch and roll fields; if GPS is not valid, the pitch and roll modes will be displayed as ATT.

7. Repeat steps 3 through 6 using pilot grip and copilot grip LVL switches.
8. Press & hold the pilot grip FTR switch and verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):



9. Repeat step 8 for copilot grip FTR switch, if installed.
10. Turn battery and avionics switches off.
11. Remove external power from helicopter.


22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

D. Upper Mode Tests


NOTE

The following procedure requires air data test equipment (Barfield DPS450 pitot-static test set or equivalent). Operate test equipment per manufacturer’s instructions.

1. Apply external power to helicopter.
2. Pressurize hydraulics per § 12-34 steps 1 thru 3.
3. Rotate cyclic friction knob full off. Move flight controls thru full travel to ensure there is no interference or binding.
4. Set the air data test equipment to 3000 feet altitude & 65 knots airspeed and allow the air data test set to stabilize at the target altitude and airspeed.
5. Engage the GFC 600H system by pressing the FCS key or press and hold the FTR switch.
6. Lift collective stick mid-travel or until the GMC no longer displays “ON GROUND”.
7. Rotate the heading bug on the HSI to the current helicopter heading.
8. Move the Selected Altitude Bug to 4500 feet altitude.
9. Press and release the FCS OFF switch to ensure that no upper mode is active.



10. Press the HDG and IAS keys to couple the upper modes. Verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):



11. Verify cyclic stick is stationary.

NOTE

There may be slight cyclic lateral motion if the helicopter is not on level ground.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)


D. Upper Mode Tests (continued)

NOTE
The following steps test lateral coupled upper modes.

12. Adjust the heading bug on the HSI to the left and verify cyclic stick moves left.
13. Adjust the heading bug on the HSI to the right and verify cyclic stick moves right.
14. Restore the heading bug on the HSI to the current helicopter heading and verify cyclic stick is centered.
15. Using the TRIM ADJUST switch, press left and verify the heading bug adjusts counter-clockwise on the HSI and the cyclic stick moves left.
16. Using the TRIM ADJUST switch, press right and verify the heading bug adjusts clockwise on the HSI and the cyclic stick moves right.
17. Restore the heading bug on the HSI to the current helicopter heading and verify cyclic stick is centered.

NOTE
The following steps test vertical coupled upper modes.


18. Rotate the NOSE UP/DN thumbwheel in the NOSE UP direction to decrease the IAS reference and verify cyclic stick moves aft.
19. Rotate the NOSE UP/DN thumbwheel in the NOSE DN direction to increase the IAS reference and verify cyclic stick moves forward.
20. Repeat steps 18 and 19 using the pilot grip TRIM ADJUST switch.
21. Press and hold the FTR switch and center the cyclic stick. This will restore the IAS reference to 65 knots.
22. Press the ALT key on the GMC. Confirm that the pitch reference matches the current altitude on the tape. The altitude reference will be displayed on the PFD next to the ALT mode annunciation and on the GMC in the pitch mode field.



22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)


D. Upper Mode Tests (continued)

23. Press the VS key on the GMC. VS should engage with a reference of 0 FPM. Confirm the active pitch mode is VS.




24. Decrease airspeed to 40 KTS indicated airspeed using air data test equipment.

25. Confirm the system enters low speed protection. In this mode of operation, the active mode on the GMC and GDU will show “IAS” with a reference of 45 KTS. If the system does not immediately enter low speed protection mode, adjust the VS reference in the direction of pitch up (positive) until the system annunciates “LOW SPD”.



26. Increase airspeed to Vne using air data test equipment and confirm the system enters MAXSPEED. If this does not occur, use the NOSE UP/DN thumbwheel to increase the pitch down (negative) VS reference until the system enters MAXSPEED.



27. Increase airspeed on the test set to above Vne and verify the “OVERSPEED” aural is played through the pilot headset.

28. De-select VS so that the pitch mode is in ATT.

29. Return air data test equipment to ground and remove equipment from helicopter per manufacturers instructions.

30. Turn battery and avionics switches off.

31. Disconnect hydraulic pump per § 12-34.

32. Remove external power from helicopter.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)**E. (VOR) NAV and APR Mode Tests****NOTE**

The following procedure requires air data test equipment (Barfield DPS450 pitot-static test set or equivalent). Operate test equipment per manufacturer's instructions.

NOTE

Perform the following procedures using Viavi Aeroflex IFR-4000 test equipment (or equivalent) per manufactures instructions.

1. Apply external power to helicopter.
2. Pressurize hydraulics per § 12-34 steps 1 thru 3.
3. Rotate cyclic friction knob full off. Move flight controls thru full travel to ensure there is no interference or binding. Center the cyclic stick.
4. Set the air data test equipment to 3000 feet altitude & 65 knots airspeed and allow the air data test set to stabilize at the target altitude and airspeed.
5. Engage the GFC 600H system by pressing the FCS key or press and hold the FTR switch.
6. Lift collective stick mid-travel or until the GMC no longer displays "ON GROUND".
7. Rotate the heading bug on the HSI to the current helicopter heading.

NOTE


The following steps test VOR NAV mode.

8. Simulate a VHF Omni Directional Radio Range (VOR) signal using the ramp test equipment.
9. Tune the NAV receiver to the simulated VOR frequency.
10. Set the Course Deviation Indicator (CDI) to VLOC.
11. Rotate the heading bug on the Horizontal Situation Indicator (HSI) to the current helicopter heading.
12. Rotate the course pointer bug on the CDI to the simulated VOR bearing.
13. Verify full scale deflection of the CDI by varying the selected course or the simulated VOR bearing at least 15° left and right.
14. Set the course pointer at least 15° from the simulated VOR bearing (left or right).

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

E. (VOR) NAV and APR Mode Tests (continued)

15. Press and release the FCS OFF switch to ensure that no upper mode is active.
16. Press the HDG key to couple the upper mode.
17. Press the NAV key.
18. Verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):
 - a. The status LED illuminates green next to the FCS key on the GMC 605H.
 - b. “HDG” is displayed above “VOR” on the GMC 605H.
 - c. “HDG”, “R”, “Y”, “P”, and “CPLD” are displayed in green text and “VOR” displayed in white text on the PFD.
19. Verify cyclic stick is stationary.
20. Slowly rotate the course pointer on the CDI toward the simulated VOR bearing, until the course pointer is within approximately 5° of the helicopter heading.
21. Verify the following annunciations and displays are present:
 - a. A flashing “VOR” is displayed in place of HDG on the GMC 605H for approximately 3 seconds then stops flashing.
 - b. A flashing “VOR” in green text is displayed in place of HDG on the PFD for approximately 3 seconds then stops flashing.




22. Alter the course on the CDI by at least 10° to the left of the simulated VOR bearing and verify the cyclic stick moves right.
23. Alter the course on the CDI by at least 10° to the right of the simulated VOR bearing and verify the cyclic stick moves left.
24. Restore the course pointer bug on the CDI to the simulated VOR bearing.
25. De-select the lateral mode by pressing the NAV key. “ATT” should be annunciated in the Roll field on the GMC and PFD.
26. Center the cyclic stick. If necessary, press the FTR switch to reset the ATT reference to keep the cyclic stick centered.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

E. (VOR) NAV and APR Mode Tests (continued)

NOTE
The following steps test VOR APR mode (VAPP).

- 27. Press the APR key.
- 28. Verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):



CDI is centered.

- 29. Confirm cyclic stick is stationary.
- 30. Press the HDG key on the GMC to return the active roll mode to HDG.
- 31. Continue testing per Part F, as required, or return air data test equipment to ground and remove equipment from helicopter per manufacturers instructions.
- 32. Turn battery and avionics switches off.
- 33. Disconnect hydraulic pump per § 12-34.
- 34. Remove external power from helicopter.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)**F. (LOC) NAV and APR Mode Tests****NOTE**

The following procedure requires air data test equipment (Barfield DPS450 pitot-static test set or equivalent). Operate test equipment per manufacturer's instructions.

NOTE

Perform the following procedures using Viavi Aeroflex IFR-4000 test equipment (or equivalent) per manufactures instructions.

1. Apply external power to helicopter.
2. Pressurize hydraulics per § 12-34 steps 1 thru 3.
3. Rotate cyclic friction knob full off. Move flight controls thru full travel to ensure there is no interference or binding. Center the cyclic stick.
4. Set the air data test equipment to 3000 feet altitude & 65 knots airspeed and allow the air data test set to stabilize at the target altitude and airspeed.
5. Engage the GFC 600H system by pressing the FCS key or press and hold the FTR switch.
6. Raise collective stick mid-travel or until the GMC no longer displays "ON GROUND".
7. Rotate the heading bug on the HSI to the current helicopter heading.

NOTE


The following steps test LOC NAV mode.

8. Simulate a localizer signal using the ramp test equipment.
9. Tune the NAV receiver to the simulated localizer frequency.
10. Set the CDI to VLOC.
11. Rotate the course pointer on the CDI to the current helicopter heading.
12. Simulate 2 dots (left or right) localizer deviation using the ramp test equipment.
13. Press and release the FCS OFF switch to ensure that no upper mode is active.
14. If HDG is not coupled, press the HDG key to couple the upper mode.
15. Press the NAV key.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

F. (LOC) NAV and APR Mode Tests (continued)

16. Verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):



- 17. Confirm cyclic stick is stationary.
- 18. Slowly center the localizer deviation using the ramp test equipment.
- 19. Verify the following annunciations and displays:
 - a. A flashing “LOC” is displayed in place of HDG on the GMC 605H for approximately 3 seconds then stops flashing.
 - b. A flashing green “LOC” is displayed on the PFD for approximately 3 seconds then stops flashing.

NOTE
LOC should capture around 1 dot deviation.

- 20. Apply fly-right localizer deviation (aircraft left-of course) using the ramp test equipment and verify cyclic stick moves right.
- 21. Apply fly-left deviation (aircraft right-of course) using the ramp test equipment and verify cyclic stick moves left.
- 22. Center the localizer deviation on the ramp test equipment.
- 23. De-select NAV mode on the GMC 605H.
- 24. Center the cyclic stick.


NOTE
The following steps test LOC/GS APR mode.

- 25. Rotate the course pointer on the CDI to the current helicopter heading.
- 26. Ensure the system has a valid and centered GS signal on the CDI.
- 27. Press the APR key.

22-17-2 Garmin FCS – Normal Mode Functional Checkout (continued)

F. (LOC) NAV and APR Mode Tests (continued)

28. Verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):



NOTE
The following steps test GPS NAV mode.

29. Set the CDI to GPS.
30. Enter a Direct To flight plan to a single waypoint on the GPS navigator that is generally in front of the helicopter and in line with the current helicopter heading.
31. Ensure the GPS navigator is navigating to the selected waypoint and the CDI is centered.
32. Press the NAV key on the GMC.
33. Verify the following annunciations and displays (“Y” will only be displayed in 3-axis installation):
 - a. “GPS” is displayed on the GMC 605H.
 - b. “GPS”, “P”, “Y”, “R”, and “CPLD” are displayed in green text on the PFD.
34. Return air data test equipment to ground and remove equipment from helicopter per manufacturers instructions.
35. Turn battery and avionics switches off.
36. Disconnect hydraulic pump per § 12-34.
37. Remove external power from helicopter.

22-18 Garmin FCS – Troubleshooting

This section describes possible symptoms associated with the Garmin GFC 600H FCS and provides corresponding actions for troubleshooting. After completing the recommended action, perform ground checks per § 22-17. If any system messages persist after performing the associated troubleshooting actions, contact RHC Technical Support.

A. GMC 605H Mode Controller LED Indicator

LED (Button)	INDICATOR STATE	STATUS
FCS	Green	FCS engaged (normal operation)
	Amber	Manual disconnect (normal operation)
	Red	The FCS has automatically disengaged from the Flight Director commands. This may be due to an internal failure, loss of AHRS data inputs, or the servos are exceeding their engagement limits. Refer to Part C for troubleshoot procedures.

B. General Troubleshooting

SYMPTOM	RECOMMENDED ACTION
The FCS will not engage (FCS LED on GMC 605H does not illuminate green).	<ul style="list-style-type: none"> • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. • Verify security of GMC 605H, GFS 83, GSU 75H, and GMU 44B electrical connectors. • Ensure wiring is not damaged. • Verify the FCS OFF and FTR switches on cyclic are not stuck or shorted. • Verify wiring of FCS OFF and FTR switches from AUTOPILOT FCS (5 amp) circuit breaker to the GMC 605H and GFS 83. • Ensure all post-installation calibrations were successfully completed.
GMC 605H display is blank.	<ul style="list-style-type: none"> • Ensure the AUTOPILOT FCS (5 amp) circuit breaker is closed. • Verify security of GMC 605H electrical connectors. • Ensure the GMC 605H wiring is correct.
PFT will not pass (displayed on GMC 605H or GDU).	<ul style="list-style-type: none"> • Ensure the AUTOPILOT FCS (5 amp) and EFIS (5 amp) circuit breakers are closed. • Verify security of GMC 605H, GFS 83, GSU 75H, and GMU 44B electrical connectors. • Ensure wiring is not damaged. • Ensure the GFS 83 servo strapping for each control axis is correct. • Ensure servos were installed in the correct location if removed from helicopter. • Ensure push-pull tubes and servo connections are secure. • Verify the FCS OFF and FTR switches on cyclic are not stuck or shorted. • Verify wiring of FCS OFF and FTR switches to the AUTOPILOT FCS (5 amp) circuit breaker and GMC 605H & GFS 83. • Ensure post-installation calibrations were performed if GMC 605H, GFS 83, and GSU 75H/GMU 44B were replaced or repaired by Garmin.
Servos will not engage (“P”, “R”, or “Y” will not display on GMC 605H when FCS button is pressed).	<ul style="list-style-type: none"> • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. • Contact RHC Technical Support.

22-18 Garmin FCS – Troubleshooting (continued)

B. General Troubleshooting (continued)

SYMPTOM	RECOMMENDED ACTION
A System Message is displayed on the GMC 605H or GDU (if installed).	<ul style="list-style-type: none"> • Troubleshoot the alert message using Part C.
R, Y, or P servo annunciations are displaying out of detent.	<ul style="list-style-type: none"> • Verify cyclic friction is off. The system may be detecting a hands on condition due to excessive friction in cyclic controls. • Verify that each AHRS (GSU 75H and GMC 605H) were calibrated at the same time and the aircraft was level at the time of calibration. • Press FTR. This will reset the reference to the current attitude. This should not be used as an initial troubleshooting step as it may not resolve the primary reason for the out of detent annunciation.
No FCS Data (On GDU)	<ul style="list-style-type: none"> • GDU not receiving data from the GMC. • Verify GMC is powered on. • Verify wiring between GMC and GDU. • Contact RHC Technical Support if issue persists.
Servo information is not being reported in Configuration mode	<ul style="list-style-type: none"> • Verify security of GFS 83 electrical connectors.
GMC 605H display does not show any status in Normal mode and the system will not engage.	<ul style="list-style-type: none"> • Reload software and ensure there are no software failures. • Contact RHC Technical Support if issue persists.
Yaw does not engage and/or disengage.	<ul style="list-style-type: none"> • Verify FCS YAW enable/disable switch is not broken. • Verify wiring of FCS YAW and YAW TRIM switches to GMC 605H.

C. Crew Alerting System (CAS) Message Troubleshooting

CAS MESSAGE	POSSIBLE CAUSE	ACTION
PFT FAIL (FCS LED – Red)	<ul style="list-style-type: none"> • FCS OFF and/or FTR switch to the GMC 605H and GFS 83 FCS OFF pins are not powered. • Blown B304-25 fuse assembly. • Servos are not communicating or are wired incorrectly for the configured control axis position. • Invalid configuration or software loaded. • Configured gains in the GMC 605H don't match the gains in the GFS 83 servos. • Internal unit failure. • Invalid attitude data (includes AHRS monitor and attitudes outside the engage limits). 	<ul style="list-style-type: none"> • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. • Verify security of GMC 605H, GFS 83, GSU 75H, and GMU 44B electrical connectors. • Ensure wiring is not damaged. • Test or replace B304-25 fuse assembly. • Ensure the FCS OFF and FTR switches on cyclic are not stuck or shorted. • Verify wiring of FCS OFF and FTR switches to the AUTOPILOT FCS (5 amp) circuit breaker and GMC 605H & GFS 83. • Troubleshoot the GSU 75H and GMU 44B per Part E. • Reload software and ensure there are no software failures. • Contact RHC Technical Support.

22-18 Garmin FCS – Troubleshooting (continued)

C. Crew Alerting System (CAS) Message Troubleshooting (continued)

CAS MESSAGE	POSSIBLE CAUSE	ACTION
PFT	PFT will not pass.	<ul style="list-style-type: none"> • Ensure push-pull tubes and servo connections are secure. • Verify the GFS 83 servo strapping is properly configured per § 22-17 Part A. • Ensure post-installation calibrations were performed if GMC 605H, GFS 83, and GSU 75H/GMU 44B were replaced or repaired by Garmin. The following can indicate that the servo is out of its calibrated range: <ul style="list-style-type: none"> • Verify servo output arm is installed in the correct orientation. • Confirm shear fuses have not been broken on pitch and roll servos. • Servo range can be confirmed in servo data diagnostic pages. If an OOR indication is shown at any point when sweeping the controls full travel, then a new range calibration will need to be performed.
FCS FAIL (FCS LED – Red)	<ul style="list-style-type: none"> • Loss of attitude data (includes AHRS monitor and attitudes outside the engage limits). • Servos Failure. • FCS OFF switch in an invalid state. • Post installation calibration not complete. 	<ul style="list-style-type: none"> • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. • Verify security of GMC 605H, GFS 83, GSU 75H, and GMU 44B electrical connectors. • Ensure wiring is not damaged. • Verify wiring of FCS OFF and FTR switches to the AUTOPILOT FCS (5 amp) circuit breaker and GMC 605H & GFS 83. • Troubleshoot the GSU 75H and GMU 44B per Part E. • Verify pitch and roll shear fuses have not been broken. • Contact RHC Technical Support.
ADC FAIL	Air Data inputs have failed.	<ul style="list-style-type: none"> • Ensure the GMC 605H and GSU 75H connectors are securely mated to the units. • Ensure wiring is not damaged. • Ensure the pitot-static system is free of debris and obstructions. • Troubleshoot the GSU 75H and GMU 44B per Part E.
FTR	FTR switch stuck.	<ul style="list-style-type: none"> • Ensure the FTR switch on cyclic is not stuck or shorted.

22-18 Garmin FCS – Troubleshooting (continued)

C. Crew Alerting System (CAS) Message Troubleshooting (continued)

CAS MESSAGE	POSSIBLE CAUSE	ACTION
LMTQ FAIL	<ul style="list-style-type: none"> Invalid attitude data (includes AHRS monitor and attitudes outside the engage limits). Air Data inputs have failed. Servos Failure. FCS OFF and/or FTR switch in an invalid state. 	<ul style="list-style-type: none"> Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. Verify security of GMC 605H, GFS 83, GSU 75H, and GMU 44B electrical connectors. Ensure wiring is not damaged. Ensure the FCS OFF and FTR switches on cyclic are not stuck or shorted. Verify wiring of FCS OFF and FTR switches to the AUTOPILOT FCS (5 amp) circuit breaker and GMC 605H & GFS 83. Troubleshoot the GSU 75H and GMU 44B per Part E. Contact RHC Technical Support.
YAW FAIL	<ul style="list-style-type: none"> Invalid attitude data (includes AHRS monitor and attitudes outside the engage limits). Air Data inputs have failed. Servos Failure. FCS OFF, FTR, and/or Yaw ENABLE/DISABLE switch in an invalid state. 	<ul style="list-style-type: none"> Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. Verify security of GMC 605H, GFS 83, GSU 75H, and GMU 44B electrical connectors. Ensure wiring is not damaged. Ensure the FCS OFF and FTR switches on cyclic are not stuck or shorted. Verify wiring of FCS OFF and FTR switches to the AUTOPILOT FCS (5 amp) circuit breaker and GMC 605H & GFS 83. Troubleshoot the GSU 75H and GMU 44B per Part E. Contact RHC Technical Support.
MANIFEST	One or more of the GFC 600H units is not reporting the expected software and/or gains version to the GMC 605H.	<ul style="list-style-type: none"> Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. Reload software and ensure there are no software failures. Contact RHC Technical Support.
COLL FAIL	Collective Position Sensor (G356-1 transducer) has failed or Collective Position Sensor has moved beyond its calibrated range.	<ul style="list-style-type: none"> Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. Ensure the GMC 605H, GFS 83, and G356-1 transducer connectors are securely mated to the units. Ensure wiring is not damaged. Verify wire on string pot is taut and crimp has not allowed the wire to slip. Recalibrate the collective position sensor (G356-1 transducer) per § 22-16-2 Part B. If message persists, replace G356-1 transducer assembly per § 22-13.

22-18 Garmin FCS – Troubleshooting (continued)

C. Crew Alerting System (CAS) Message Troubleshooting (continued)

CAS MESSAGE	POSSIBLE CAUSE	ACTION
AHRS DGRD	GMC 605H Air Data, GPS, or Magnetometer sensor inputs are not being used. This can indicate a magnetic anomaly or loss of data input to the system. This message is not considered abnormal when on the ground or near structures with ferrous materials.	If a persistent message is observed in-flight, consider the following actions: <ul style="list-style-type: none"> • Confirm from RS-232 Port 4 or Port 5 I/O diagnostics that the GMC 605H is receiving a valid MapMX signal (check mark displayed). • Review Internal AHRS diagnostics in Configuration mode. Review the Label 271 status pages to confirm that the internal AHRS is receiving air data and GPS and that the magnetometer is not indicating any abnormal faults.
GPS DATA	The FCS is not receiving valid GPS data or required GPS aiding data.	Verify HSDB wiring and RS-232 wiring from the interfaced GPS receiver.
FCS SWITCH	The FCS OFF switch has been active for >15 seconds. The switch is disabled while this message is displayed.	<ul style="list-style-type: none"> • Ensure FCS OFF switch is not physically stuck. • Verify wiring for both NC and NO poles for the FCS OFF switches.
<PIT or ROLL> BEEP	The cyclic TRIM ADJUST switch has been active for >30 seconds.	<ul style="list-style-type: none"> • Ensure the switch is not physically stuck. • Verify wiring for pilot and copilot trim switches.
YAW BEEP	The YAW TRIM switch has been active for >30 seconds.	<ul style="list-style-type: none"> • Ensure the switch is not physically stuck. • Verify wiring for YAW TRIM switch.
LVL SWITCH	The LVL switch has been active for >30 seconds.	<ul style="list-style-type: none"> • Ensure the LVL switch is not physically stuck. • Verify wiring for LVL switches.
NO ATT	The GMC 605H internal AHRS board has not aligned. If the message persists, this can indicate a configuration error with the AHRS board. This message may be presented intermittently while PFT is being executed.	<ul style="list-style-type: none"> • If message persists without resolution, confirm the GMC internal AHRS is receiving GPS, Air Data, and Magnetometer data. • Review Internal AHRS diagnostics in Configuration mode. Review the Label 271 status pages to confirm that the internal AHRS is receiving air data and GPS and that the magnetometer is not indicating any abnormal faults. • If it can be determined that all source data is being provided, a new pitch/roll calibration and magnetometer calibration may be required. • Contact RHC Technical Support.
<ul style="list-style-type: none"> • FCS KEY • HDG KEY • NAV KEY • APR KEY • IAS KEY • VS KEY • ALT KEY • LVL KEY 	Annunciated key on the GMC 605H is stuck in the pressed state.	<ul style="list-style-type: none"> • Press the annunciated key to cycle its operation. • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker and verify PFT passes. • If message persists, replace the GMC 605H.

22-18 Garmin FCS – Troubleshooting (continued)

D. GMC 605H Configuration Mode Test Faults

ANNUNCIATED FAULT	POSSIBLE CAUSE	ACTION
TEST FAILED: TIMEOUT	Data communications failure: GMC internal AHRS did not respond for test/procedure before timeout.	<ul style="list-style-type: none"> • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker. • Ensure the GMC 605H, GFS 83, GSU 75H and GMU 44B connectors are securely mated to the units. • Ensure wiring is correct.
TEST FAILED: INVALID READY STATE	The GMC 605H internal AHRS orientation configuration is invalid or experienced an internal fault.	<ul style="list-style-type: none"> • Ensure that the configuration settings are correct per § 22-16-1 Part B. • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker. • Reload software per § 22-16-1 Part C. • Contact RHC Technical Support.
TEST FAILED: AIRCRAFT IN MOTION	<ul style="list-style-type: none"> • Helicopter is moving. • GMC 605H is being subjected to excessive vibration. • The GMC 605H is not receiving valid GPS or Air Data. • An internal error has occurred with the GMC 605H AHRS sensor. 	<ul style="list-style-type: none"> • Ensure the helicopter is stationary. • Ensure the GMC 605H is mounted securely and is sufficiently rigid. • Ensure a valid GPS and Air Data source is available to the GMC 605H. • Ensure that the configuration settings are correct per § 22-16-1 Part B. • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker. • Ensure the GMC 605H, GFS 83, GSU 75H, and GMU 44B connectors are securely mated to the units. • Ensure wiring is correct. • Contact RHC Technical Support.
TEST FAILED: GMU NOT CALIBRATED	GMU 44B magnetic calibration is not done.	<ul style="list-style-type: none"> • Complete magnetometer calibration and retry procedure. • If message persists, return GMU 44B unit to RHC.
TEST FAILED: GRS NOT CALIBRATED	The GMC internal AHRS has experienced a calibration error.	Replace the GMC 605H unit.
TEST FAILED: GMC AHRS PIT/ROL NOT CALIBRATED	The GMC internal AHRS pitch/roll calibrations have not been completed.	<ul style="list-style-type: none"> • Complete pitch/roll calibration then retry procedure. • If message persists, contact RHC Technical Support.
TEST FAILED: INVALID TILT	The internal GMC 605H AHRS sensor has experienced an accelerometer failure.	<ul style="list-style-type: none"> • Ensure that the configuration settings are correct per § 22-16-1 Part B. • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker. • Contact RHC Technical Support. • If message persists, replace the GMC 605H unit.

22-18 Garmin FCS – Troubleshooting (continued)

D. GMC 605H Configuration Mode Test Faults (continued)

ANNUNCIATED FAULT	POSSIBLE CAUSE	ACTION
TEST FAILED: GPS & GMU MEASUREMENT FAILURE	The GMC is not receiving GPS and GMU sensor data.	<ul style="list-style-type: none"> • Ensure the helicopter is stationary. • Ensure the GMC 605H is mounted securely and is sufficiently rigid. • Ensure a valid GPS and Air Data source is available to the GMC 605H. • Ensure that the configuration settings are correct per § 22-16-1 Part B. • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker. • Ensure the GMC 605H, GFS 83, GSU 75H, and GMU 44B connectors are securely mated to the units. • Ensure wiring is correct. • Contact RHC Technical Support.
TEST FAILED: MAGNETOMETER MEASUREMENT FAILURE	The GMC is not receiving GMU sensor data.	
TEST FAILED: GPS MEASUREMENT FAILURE	The GMC is not receiving GPS data.	
TEST FAILED: UNKNOWN MEASUREMENT FAILURE	The GMC is receiving GPS and GMU sensor data, but data is invalid.	
TEST FAILED: UNKNOWN FAILURE	An internal error has occurred with the GMC 605H AHRS sensor.	<ul style="list-style-type: none"> • Ensure that the configuration settings are correct per § 22-16-1 Part B. • Pull open AUTOPILOT FCS (5 amp) circuit breaker and wait for display to turn off completely. Push in circuit breaker. • Reload software per § 22-16-1 Part C. • Contact RHC Technical Support. • If message persists, replace the GMC 605H unit.
TEST FAILED: INVALID PITCH OFFSET	The pitch offset value is outside the predefined range (e.g., a zero pitch/roll calibration with a non-zero pitch value).	<ul style="list-style-type: none"> • Ensure the helicopter is level and repeat the calibration test. • If message persists, replace the GMC 605H unit.
TEST FAILED: INVALID ROLL OFFSET	The roll offset value is outside the predefined range (e.g., a zero pitch/roll calibration with a non-zero roll value).	<ul style="list-style-type: none"> • Ensure the helicopter is level and repeat the calibration test. • If message persists, replace the GMC 605H unit.
TEST FAILED: RESULT NOT SAVED	The GMC 605H has experienced an internal non-volatile memory error.	<ul style="list-style-type: none"> • Replace GMC 605H configuration module. • Contact RHC Technical Support.
TEST FAILED: CRC FAILED	The GMC 605H received invalid data.	<ul style="list-style-type: none"> • Ensure that the configuration settings are correct per § 22-16-1 Part B. • Ensure a valid GPS and Air Data source is available to the GMC 605H. • Ensure the GMC 605H, GFS 83, GSU 75H, and GMU 44B connectors are securely mated to the units. • Ensure wiring is correct.

22-18 Garmin FCS – Troubleshooting (continued)

D. GMC 605H Configuration Mode Test Faults (continued)

ANNUNCIATED FAULT	POSSIBLE CAUSE	ACTION
TEST FAILED: • MAG-FIELD RETURNED BAD RESULTS • HORIZONTAL MAG FIELD TOO SMALL • PHASE I / II NOT COMPLETED FAST ENOUGH • TOO MANY STATIONS AROUND COMPASS ROSE • NOT ENOUGH N,E,S,W STATION DATA • COMPUTED MAGNETIC OFFSETS ARE TOO LARGE • SITE DOESN'T HAVE UNIFORM MAGNETIC FIELD • SITE MAG FIELD DIFFERENT FROM IGRF MODEL	• GMC is not receiving valid GPS, air data, and/or magnetometer data. • Helicopter is not in a magnetically clean area. • Post-install calibrations were not completed.	• Ensure that the configuration settings are correct per § 22-16-1 Part B. • Ensure a valid GPS and Air Data source is available to the GMC 605H. • Ensure the GMC 605H, GFS 83, GSU 75H and GMU 44B connectors are securely mated to the units. • Ensure wiring is correct. • Ensure helicopter is in an area free of magnetic interference and away from ferrous metal objects. • Ensure all calibration procedures were completed in order.

E. AHRS/ADC Faults

FAULT MESSAGE	POSSIBLE CAUSE	ACTION
AHRS 1/2 reports an in-tarmac magnetic anomaly	The AHRS has detected an in-tarmac anomaly at the given location.	• If this error shows up repeatedly, conduct the magnetic interference check. • If fault persists, contact RHC Technical Support.
AHRS 1/2 reports a local earth magnetic anomaly	The AHRS has detected a local earth anomaly at the given location.	• If this error shows up repeatedly, conduct the magnetic interference check. • If fault persists, contact RHC Technical Support.
AHRS 1/2 magnetic model database needs update	The designated AHRS Magnetic Model is out-of-date.	• Update the magnetic model database. • If fault persists, contact RHC Technical Support.
AHRS 1/2 not receiving valid magnetometer data	Communication lost with GMU 44B or GMU 44B installation incorrect.	• If other ADC or AHRS faults are present, correct those first. • Verify ADC 1/2 configuration and wiring. • If fault persists, contact RHC Technical Support.
ADC 1/2 error correction inoperative	The alert flag has been set by the ADC.	• If other ADC or AHRS faults are present, correct those first. • Verify ADC 1/2 configuration and wiring. • If fault persists, contact RHC Technical Support.
Service required	ADC loss of communication or no GTP 59 signal.	• Verify ADC power. • Inspect ADC/AHRS wiring and connections. • Inspect GTP 59 connections and wiring. • If fault persists, contact RHC Technical Support.

22-18 Garmin FCS – Troubleshooting (continued)

F. Post Installation Calibration Troubleshooting

ANNUNCIATED FAULT	POSSIBLE CAUSE	ACTION
ERROR – Error occurred while starting <procedure name>	The GSU 75H experienced a mode swap error (i.e., sensor is not in configuration mode to perform the post-install procedure).	<ul style="list-style-type: none"> • Ensure 60 seconds has passed from navigating from the Main Menu to the AHRS Menu and rerun procedure. • Cycle power to the sensor.
Cannot start <procedure name> until aircraft is stationary	Helicopter is not stationary.	<ul style="list-style-type: none"> • Ensure helicopter is stationary. • Ensure GPS has an unobstructed view of the sky. • Ensure the GSU 75H is not subject to excessive vibration. • Rerun procedure.
Timeout occurred while starting <procedure name>	AHRS did not respond for test/procedure before internal timeout.	Cycle power to the GSU 75H and ensure 60 seconds has passed from navigating from the Main Menu to the AHRS Menu and rerun procedure.
Unable to begin <procedure name>	AHRS did not respond with correct calibration procedure reply.	Cycle power to the GSU 75H and ensure 60 seconds has passed from navigating from the Main Menu to the AHRS Menu and rerun procedure.
Timeout occurred while completing <procedure name>	AHRS did not reply complete for the test/procedure before timeout.	<ul style="list-style-type: none"> • Ensure the GSU 75H is receiving valid GPS and Magnetometer (green check). • Cycle power to unit and retry procedure.

22-18 Garmin FCS – Troubleshooting (continued)

G. Upload and Download Troubleshooting

ANNUNCIATED FAULT	POSSIBLE CAUSE	ACTION
Invalid <any region> download	Region read error	Cycle power on the GSU 75H and retry download.
Error upload/downloading <any region>: <reason>	Fail	Cycle power on the sensor and retry download.
	File open failure	Ensure the download location is valid and has read/write access.
	Empty region	Data does not exist or is corrupt and retry download.
	Region not fully downloaded	Cycle power to the sensor and retry download.
	Timeout	Cycle power to the sensor and retry download.
	<ul style="list-style-type: none"> • Unit disconnected OR • Dropping packets due to poor connection 	Cycle power to the sensor and retry download.
No flight logs downloaded. Press OK to return...	The GSU 75H did not respond with flight log before timing out.	Cycle power on the sensor and retry download.
Flight Log download was not successful: Download directory is invalid	Download location is not valid to save file.	Ensure the download location is valid and has read/write access and retry download.
Flight Log download was not successful: Unexpected error	Issue populating the flight log table.	Cycle power on the sensor and retry download.
Unable to start Flight Log download: No flight logs selected	No flight log was selected to download.	Select a flight log and retry download.
Download AHRS Config is corrupt. Please upload valid AHRS Config and try again.	AHRS config is corrupt or invalid.	<ul style="list-style-type: none"> • Upload a new AHRS config file and retry. • Ensure AHRS configuration matches airframe configuration. Resetting configuration may be necessary if reloading a config file.
Cannot upload an AHRS Config with invalid AHRS Orientation. Please select valid AHRS orientation and try again.	AHRS orientation not selected in AHRS configuration settings.	Ensure that the configuration settings are correct per § 22-16-1 Part B.

22-20 HeliSAS (Stability Augmentation System)

22-21 HeliSAS – Description

The HeliSAS autopilot system consists of two electric servomotors, a flight control computer, an autopilot control panel, and control buttons on the cyclic grip. One servomotor controls pitch and is installed in the control tunnel forward of the cyclic stick. The other servomotor controls roll and is installed under the pilot's seat. The servomotors are connected to the cyclic through electromagnetic clutches.

The flight control computer is installed on the forward panel under the pilot's seat, and the autopilot control panel is installed in the avionics stack.

The autopilot senses aircraft attitude using a combination of sensors in the flight control computer and an independent onboard attitude source such as the Attitude Heading Reference System (AHRS) for the Primary Flight Display (PFD). The computer then sends signals to the servomotors which are connected to the bottom of the cyclic in the control tunnel.

The primary autopilot mode is Stability Augmentation System (SAS) mode which maintains a steady helicopter attitude by applying corrective inputs to the cyclic. This is felt as a light cyclic centering force. Additional modes may be layered on top of SAS mode and are described below. The pilot can override as desired for maneuvering without disengaging the system. Only a few pounds of force at the cyclic are required for override, and the system will not disconnect due to pilot cyclic inputs.

The control panel has a row of buttons to control autopilot modes and annunciators to indicate mode status. A dark annunciator indicates that a mode is off, a white annunciator indicates that a mode is armed or on standby, and a green annunciator indicates that a mode is active.

When the avionics master is switched on, the autopilot performs a self-test and then enters SAS standby mode. All of the control panel indicators flash alternating white and green during the self-test. Four headset beeps occur at the beginning of the self-test as a check of the aural warning function. The SAS annunciator on the control panel turns steady white when the self-test is complete.

NOTE

Autopilot will not enter standby mode if attitude indicator is not functioning or indicated bank angle is greater than 6 degrees.

The autopilot SAS mode is engaged either by pressing the SAS button on the control panel or by pressing the TRIM button on the cyclic for more than 1.25 seconds. Additional modes are engaged by pressing the appropriate button on the control panel. The additional modes are disabled and will not engage at airspeeds below 44 KIAS or above 140 KIAS.

22-21 HeliSAS – Description (continued)

To disengage any mode, push the appropriate button on the control panel.

NOTE

Disengaging SAS mode will also disengage all other modes.

Modes may also be disengaged using the AP OFF button on the cyclic. If only SAS mode is engaged, push the AP OFF button once to disengage. If additional modes are engaged, push the AP OFF button once to disengage all modes except SAS and a second time to disengage SAS mode, or push and hold the AP OFF button to disengage all modes including SAS.

NOTE

SAS disengagement should always be accompanied by four beeps in the headset. If beeps do not occur, maintenance is required.

Safety monitors automatically disengage individual modes or the entire system if a fault is detected. Automatic disengagement of SAS mode (or the entire system) is indicated by four beeps in the headset. Automatic disengagement of any mode other than SAS is indicated by a single beep in the headset. There is no audio indication for intentional disengagement of modes other than SAS.

NOTE

The system also automatically reverts to SAS mode at airspeeds below 44 KIAS or above 140 KIAS, accompanied by a single beep. The high speed limit is not intended to provide V_{ne} protection. It is the pilot's responsibility to observe V_{ne} limits.

The TRIM button is used to re-set the target attitude (to re-trim) while in SAS mode. Use a small amount of force to override the autopilot and then push and release the TRIM button at the new desired condition. If the force to override is objectionable, the TRIM button may be held down during maneuvers. The system will re-trim to the attitude at which the TRIM button is released. For Version 52, stick forces felt during override will gradually wash out to near zero without use of TRIM button if override is maintained.

NOTE

The system will not re-trim to angles more than approximately 10° in pitch or roll.

22-21 HeliSAS – Description (continued)

NOTE

When engaging SAS mode from standby, for angles of less than approximately 10° in pitch and roll, SAS holds the current angles. If either pitch or roll is larger than approximately 10°, the system assumes an unusual attitude and gently levels the helicopter.

The autopilot is protected by a dedicated circuit breaker on the avionics bus (autopilot is not powered with the avionics master switch off).

Heading Mode (HDG) – maintains the heading selected by the heading bug on the directional gyro or Horizontal Situation Indicator (HSI) display. Aircraft can be steered using the heading bug.

Altitude Mode (ALT) – maintains altitude at the time of engagement or of last TRIM button release. The target altitude is reset each time the TRIM button is pressed and released.

NOTE

The autopilot uses pitch attitude to maintain altitude or follow an approach glidepath. It does not have any control of power setting. The pilot must manage power with the collective to control speed and rate of climb or descent. Make small, smooth power changes to allow the system to adjust to new power settings.

Navigation Mode (NAV) – tracks the active GPS or VLOC course displayed on the Course Deviation Indicator (CDI). If no CDI is installed, NAV will only track the active GPS course displayed on the GPS.

NAV may be armed prior to intercepting the active course. NAV annunciator is white when NAV is armed and turns green at course intercept. If HDG is active when NAV is armed, the autopilot will fly the selected heading until course intercept. If HDG is not active, the autopilot will select a 45° intercept angle.

| 22-21 HeliSAS – Description (continued)

Vertical Navigation Mode (VRT) – tracks an ILS glideslope or GPS approach vertical guidance. Arm VRT (annunciator turns white when armed) prior to intercepting the glidepath. VRT annunciator will turn green at glidepath intercept.

NOTE

Pushing the ALT button while VRT is armed or active will turn off VRT. VRT must be re-armed or re-engaged as desired.

NOTE

Reducing power to approach setting just prior to glidepath intercept is recommended.

Speed Mode (SPD) (Version 52 only)

Speed mode uses cyclic pitch to control airspeed. Exact behavior varies with configuration of airspeed and altitude bugs on the PFD as described below.

The altitude bug is displayed above the altitude tape and the airspeed bug is displayed above the airspeed tape. The appearance of all dashes or a blank field indicates a bug is not set.

If an airspeed bug is not set, selecting SPD holds the current airspeed. The target speed is reset each time the trim button is pressed and released.

If an airspeed bug is set, selecting SPD holds airspeed at the bug setting. Changing the bug will change the target airspeed.

If an altitude bug is set, selecting SPD will also arm ALT (ALT LED white) for altitude capture. The mode will switch from SPD to ALT if the selected altitude is crossed. There will be a brief period in capture mode with the ALT LED flashing white/green.

NOTE

Do not change the selected altitude during ALT capture (ALT LED flashing white/green). System may pitch up or down to chase bug and may not capture altitude.

NOTE

Different brands of PFD behave differently in terms of bug settings at power up and how bugs are manually set. Refer to PFD manufacturer’s documents for proper use. Verify desired bug settings before engaging SPD mode.

22-21 HeliSAS – Description (continued)

Backcourse Mode (BC) (Version 51 only) – reverse CDI sensing for backcourse approaches. Course on HSI should be set so that tail of course pointer points toward runway (set to inbound front course).

Airspeed Protection (Version 52 only) – Minimizes the possibility of the ALT mode to fly the helicopter to an airspeed below 44 KIAS due to insufficient power, or the VRT mode to fly the helicopter to an airspeed above 140 KIAS due to excess power when flying a precision approach glideslope. When triggered, it causes the longitudinal mode to change from ALT (at low airspeed) or VRT (at high airspeed) to SAS mode with a commanded pitch attitude of 2 degrees nose down. Since the mode change is not commanded by the pilot, a single warning beep is annunciated.

A. Removable Flight Controls

On later aircraft, disconnect the electrical connector for the left-hand trim button located near the quick release pin before removing the left cyclic grip. Reconnect the connector when installing the left cyclic grip.

B. Schematic

Refer to Figures 98-8B & 98-8C for D325-1 autopilot (HeliSAS) electrical schematic.




FIGURE 22-8 HELISAS AUTOPILOT SYSTEM

22-22 HeliSAS – (Pitch) Servo Assembly**A. Removal**

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel.
2. Remove F680-3 and F445 collective covers and F444-1 cyclic cover. Hinge front right seat forward. Remove G702 cover assembly under pilot's seat.
3. Remove avionics and avionics trays as required from lower console.

CAUTION

For pitch servo, adjust length of A336-8 push-pull tube assembly to 4.20 ± 0.03 inches between rod end centers.

4. Position cyclic stick full aft and apply cyclic friction. Remove hardware (and C130-50 spacer) securing 01317-3 (pitch) servo assembly arm to A336-8 push-pull tube's rod end.
5. Disconnect servo harness from flight control computer's J1 PITCH receptacle. Cut and discard ty-rap(s) securing harness to M23190/1-2 clamp(s) and pull harness through access holes into control tunnel.
6. Support servo and remove hardware securing servo's brace to cyclic box and keel panels. Carefully remove servo from control tunnel.

B. Installation

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel. Position cyclic stick full aft and apply cyclic friction.
2. Position 01317-3 (pitch) servo assembly in control tunnel and install hardware securing servo's brace to cyclic box. Standard torque bolts per § 20-32 and torque stripe per Figure 5-1. Install screws securing brace to keel panels. Verify security.
3. Route servo harness through access holes and connect harness to flight control computer's J1 PITCH receptacle. Install ty-rap(s) securing harness to M23190/1-2 clamp(s). Cinch ty-raps until snug without over-tightening, and trim tips flush with heads. Verify harness security.
4. Install hardware (and C130-50 spacer) securing servo arm to A336-8 push-pull tube's rod end. Standard torque bolt per § 20-32 and torque stripe per Figure 5-1. Verify security.
5. Verify length of A336-8 push-pull tube assembly connected to pitch servo is 4.20 ± 0.03 inches between rod end centers.
6. Verify freedom of flight controls through full travel with and without friction applied.
7. Install avionics trays and avionics if removed. Verify security.
8. Push in AUTOPILOT circuit breaker (5 amp) at panel. Perform ground checks as appropriate per § 22-27 Part A.
9. Install G702 cover assembly under pilot's seat. Install F444-1 cyclic cover, and F445 and F680-3 collective covers. Verify security.

22-23 HeliSAS – (Roll) Servo Assembly

A. Removal

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel.
2. Remove F680-3 and F445 collective covers. Remove G702 cover assembly under pilot's seat.

CAUTION

For roll servo, adjust length of A336-8 push-pull tube assembly to 4.30 ± 0.03 inches between rod end centers.

3. Position cyclic stick full left and apply cyclic friction. Remove hardware securing 01317-4 (roll) servo assembly arm to A336-8 push-pull tube's rod end.
4. Disconnect servo harness from flight control computer's J3 ROLL receptacle. Cut and discard ty-raps securing servo harness to autopilot harnesses.
5. Support servo and remove hardware securing servo's block assembly to keel panel and brace assembly. Carefully remove servo from under pilot's seat.

B. Installation

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel. Position cyclic stick full left and apply cyclic friction.
2. Position 01317-4 (roll) servo assembly under pilot's seat and install hardware securing servo's block assembly to keel panel and brace assembly. Tighten screws. Verify security.
3. Connect servo harness to flight control computer's J3 ROLL receptacle. Install ty-raps securing servo harness to autopilot harnesses as required. Cinch ty-raps until snug without over-tightening, and trim tips flush with heads. Verify harness security.
4. Install hardware securing servo arm to A336-8 push-pull tube's rod end. Standard torque bolt per § 20-32 and torque stripe per Figure 5-1. Verify security.
5. Verify length of A336-8 push-pull tube assembly connected to roll servo is 4.30 ± 0.03 inches between rod end centers.
6. Verify freedom of flight controls through full travel with and without friction applied.
7. Push in AUTOPILOT circuit breaker (5 amp) at panel. Perform ground checks as appropriate per § 22-27 Part A.
8. Install G702 cover assembly under pilot's seat. Install F445 and F680-3 collective covers. Verify security.




FIGURE 22-9 FLIGHT CONTROL COMPUTER

Version 51		Version 52	
FCC part number	01311-03-11	FCC part number	01311-02-111
Control panel part number	01309-01-01	Control panel part number	01309-03-01

TABLE 22-2 SOFTWARE VERSIONS AND EQUIPMENT PART NUMBERS

22-24 HeliSAS – Flight Control Computer (FCC)

NOTE

Refer to Table 22-2. Flight control computer (FCC) and control panels for Software Version 51 and Software Version 52 are not interchangeable. Verify part number compatibility prior to installation.

22-24 HeliSAS – Flight Control Computer (FCC; continued)**A. Removal**

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel.
2. Remove G702 cover assembly under pilot's seat.
3. Disconnect D323 harness assemblies and servo assembly harnesses from flight control computer's J1 PITCH, J2, J3 ROLL, and J4 receptacles.
4. Support computer and remove screws securing computer to D358 support assemblies. Carefully remove computer from under pilot's seat.

B. Installation**NOTE**

Prior to installation, verify affected FCCs were upgraded per R66 SB-37.

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel.
2. Position flight control computer under pilot's seat and install screws securing computer to D358 support assemblies. Tighten screws. Verify security.
3. Ensure pitot and static ports on FCC are capped.
4. Connect D323 harness assemblies and servo assembly harnesses to computer's J1 PITCH, J2, J3 ROLL, and J4 receptacles. Install ty-raps securing harnesses as required. Cinch ty-raps until snug without over-tightening, and trim tips flush with heads. Verify harness security.
5. Verify freedom of flight controls through full travel with and without friction applied.
6. Push in AUTOPILOT circuit breaker (5 amp) at panel. Perform ground checks as appropriate per § 22-27 Part A.
7. Install G702 cover assembly under pilot's seat.

22-25 HeliSAS – Control Panel**NOTE**

Refer to Table 22-2. Flight control computer (FCC) and control panels for Software Version 51 and Software Version 52 are not interchangeable. Verify part number compatibility prior to installation.

22-25 HeliSAS – Control Panel (continued)**A. Removal**

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel.
2. Loosen quarter-turn fasteners securing control panel to console assembly.
3. Carefully unplug harness from control panel and remove panel.

B. Installation

1. Turn battery & avionics switches off and pull out AUTOPILOT (5 amp) circuit breaker at panel.
2. Carefully plug-in harness to control panel.
3. Tighten quarter-turn fasteners securing control panel to console assembly. Verify security.
4. Push in AUTOPILOT circuit breaker (5 amp) at panel. Perform ground checks as appropriate per § 22-27 Part A.

22-26 HeliSAS – Cyclic Grip Assembly**A. Grip Angle Adjustment**

1. Loosen cap screws securing pilot's cyclic grip, block assembly, and bar to grip weldment.
2. Rotate grip about weldment to desired angle. Special torque cap screws to 40 in.-lb.

B. Removal and Installation

To access grip switches:

1. Remove MS24693-S1 screws securing C214-27 plate to D379-1 grip. Remove switch nuts and lockwashers to free switches from plate.
2. Install switch lockwashers (new) and nuts and tighten switches to plate; verify switch security. Install screws securing plate to grip.
3. Turn battery switch on and perform ground checks as appropriate per § 22-27 Part A.

C. Schematic

Refer to Figure 98-1 for F024 electrical system schematic.

22-27 HeliSAS – Maintenance

A. Ground Checks

NOTE

Perform the following ground checks after component replacement or other repairs have been performed on the autopilot system. Perform ground checks after any incident that may have affected autopilot or related equipment prior to return to service.


NOTE

Refer to § 22-27 Part B for troubleshooting if any of the following ground checks cannot be verified.

1. Turn battery & avionics switches on. Verify four beeps in headset and control panel LEDs alternate white/green:



FOUR BEEPS
IN HEADSET




LEDs ALTERNATE
WHITE/GREEN

(01309-01-01 control panel shown)

2. Verify SAS enters standby mode approximately 6 seconds after PFD aligns. Verify no sound in headset and control panel SAS LED is white, other LEDs are dark:



NO SOUND




SAS LED IS WHITE,
OTHER LEDs DARK

3. With cyclic friction full off, verify cyclic moves freely within hydraulic servo longitudinal and lateral deadbands.
4. Engage SAS mode (cyclic should feel "energized"). Verify no sound in headset and control panel SAS LED is green, other LEDs are dark:



NO SOUND



SAS LED IS GREEN,
OTHER LEDs DARK

5. With SAS engaged, displace cyclic at least 1 inch from neutral position and verify a vibrating resistance is encountered. Perform check for roll & pitch axes.


22-27 HeliSAS – Maintenance (continued)

A. Ground Checks (continued)

- Refer to step 2. Engage SAS and verify SAS disengages when control panel's SAS button is depressed or when AP OFF button on the cyclic grip is depressed. Verify four beeps in headset and control panel SAS LED is white, other LEDs are dark:



FOUR BEEPS
IN HEADSET




SAS LED IS WHITE,
OTHER LEDS DARK

- Perform pitot system leak test per § 95-10 and, while airspeed indicates > 50 knots: Engage SAS and ALT modes. Verify no sound in headset and SAS & ALT LEDs are green, other LEDs are dark:



NO SOUND




SAS & ALT LEDS ARE
GREEN, OTHER LEDS
DARK

- Disengage ALT mode. Verify no sound in headset and SAS LED is green, other LEDs are dark:



NO SOUND



SAS LED IS GREEN,
OTHER LEDS DARK

- Refer to steps 7 & 8. Engage SAS and HDG modes. Verify no sound in headset and SAS & HDG LEDs are green, other LEDs are dark. Disengage HDG mode. Verify no sound in headset and SAS LED is green, other LEDs are dark.
- Engage SAS, HDG, and ALT modes. Verify no sound in headset and SAS, HDG, and ALT LEDs are green, other LEDs are dark. Press AP OFF button on cyclic grip. Verify no sound in headset and SAS LED is green, other LEDs are dark.
- Engage SAS, HDG, and ALT modes. Verify no sound in headset and SAS, HDG, and ALT LEDs are green, other LEDs are dark. Press AP OFF button twice on cyclic grip. Verify four beeps in headset and SAS LED is white, other LEDs are dark.

22-27 HeliSAS – Maintenance (continued)

B. Troubleshooting

CAUTION
Adjustment to autopilot equipment is not permitted.

PROBLEM	ACTION
Control panel lights do not illuminate or flash when master switch is turned on.	Verify computer is getting power.
	Return computer to RHC.
System does not enter standby-mode (lights flash continuously).	Verify attitude indicator bank angle less than 6 degrees.
	Verify attitude indicator output between 13 and 14 pins is less than 0.3 volts at connector.
	Check wiring between attitude indicator and computer.
	Contact RHC Technical Support.
SAS does not engage when TRIM button depressed for longer than 1.25 seconds; pressing TRIM button does not reset reference attitude; pressing TRIM button does not reset reference altitude in altitude hold.	Check wiring between TRIM button and computer.
	Verify integrity of TRIM button.
	Return computer to RHC.
SAS does not disengage when cyclic grip AP OFF button depressed.	Check wiring between AP OFF button and computer.
	Verify integrity of AP OFF button.
	Return computer to RHC.
SAS does not engage or disengage when control panel buttons pressed.	Engage and/or disengage SAS using cyclic grip buttons. If system responds properly, failure is in control panel or associated wiring to computer.
	Contact RHC Technical Support.
SAS does not hold pitch attitude, but holds roll attitude or vice versa.	Check servo-to-cyclic linkage.
	Check wiring between faulty servo and computer.
	Return faulty servo and computer to RHC.
SAS disengages unintentionally (accompanied by four beeps in headset).	Contact RHC Technical Support.
Autopilot mode disengages unintentionally, and reverts to SAS mode (accompanied by single beep in headset).	Determine if navigation signal may have gone invalid due to operational reason.
	Check wiring between appropriate instrument/avionics and computer.
	Check instrument/avionics for failure flags (steady and intermittent).
Cyclic vibrates erratically, SAS does not disengage.	Manually override SAS, system should disengage automatically.
	Contact RHC Technical Support.
Helicopter enters low frequency pitch oscillation when ALT engaged; helicopter diverges nose-up or nose-down when ALT engaged.	Return computer to RHC.

22-27 HeliSAS – Maintenance (continued)

B. Troubleshooting (continued)

PROBLEM	ACTION
ILS glideslope tracking performance is poor.	Check for excessive friction in longitudinal cyclic. Check GPS output to computer.
Cyclic force seems higher than normal with SAS disengaged.	Verify servo clutches are disengaged, and clutch arms do not move when SAS is Off or in standby-mode.
No aural warning in headset when SAS is disengaged.	Check wiring to unswitched audio input to audio panel.

Intentionally Blank

28-60 Pressure Fueling System

A. Description

The pressure fueling system consists of a fueling port on the right side of the fuselage, two shut-off valves in series just downstream of the port, a hose from the valves to an inlet at the top of the fuel tank, fuel tank level and pressure sensors, and a control panel on the instrument panel. The fueling port is compatible with an Emco Wheaton J71 dry-break coupler (recommended Emco Wheaton part no. J71C-AVN1-E004, which fits a fuel hose with a one inch male NPT threaded fitting).

Two shut-off valves are used to provide redundant protection against overfueling. Both valves must be open to allow fuel to flow. Each valve is connected to an independent float switch in the fuel tank to close the valve when the tank is full as well as an independent pressure switch to close the valve if fuel tank overpressure is detected. One of the valves is also connected to a second float switch to shut off at 25 gallons (95 liters).

The pressure fueling control panel includes a power switch, a quantity selector switch, a VALVE OPEN light, and a TANK PRESSURE warning light with two test buttons for testing the overpressure warning circuits. The power switch enables refueling by providing power to open the two shut-off valves. If the helicopter is running, the collective must be on the down stop for the valves to operate. The VALVE OPEN light illuminates when both shut-off valves are open, indicating the system is ready to accept fuel. The TANK PRESSURE light illuminates when excessive pressure is detected in the fuel tank. Excessive pressure will latch a shut-off valve closed until power to the system is cycled.

The pressure fueling system feeds fuel to the top of the main fuel tank. The system cannot be used for defueling and it will not add fuel to the optional auxiliary tank in the baggage compartment. Maximum allowable pressure for ground equipment connected to the fueling port is 50 psi (3.5 bar), which provides approximately 50 gallons per minute (190 liters per minute) fuel flow. Approximate flow rates at lower pressures are 30 gpm at 20 psi, 20 gpm at 10 psi, and 100 lpm at 1 bar.

The fueling port and recommended Emco Wheaton coupler are both dry-break fittings, allowing the external fueling equipment to be connected or disconnected without fuel spillage regardless of whether the shut-off valves are open or closed. A cap is provided which may be installed on the fueling port when the system is not in use.

An optical sensor near the fueling port will detect a fuel hose if the hose is connected to the port. If the collective is raised off the down stop while a hose is connected, a "fuel hose" audio alert will repeat in the headsets. The alert is muted 15 seconds after the collective is raised to prevent a distraction in case of a false alert.

CAUTION

The audio alert is only an aid. Do not rely on audio alert to verify hose is disconnected. Pilots must visually confirm fuel hose is disconnected and area is clear before takeoff.




FIGURE 28-8 MAIN FUEL PORT (SHOWN WITH OPTIONAL AUX FUEL TANK)

28-61 A521 (Fuel Level) Switch Assemblies**CAUTION**

Avoid contaminating bladder interior. Cover arms with sleeves and use lint-free gloves when working inside bladder.

A. Schematic

Refer to Figure 98-34 for pressure fueling system installation schematic.

B. Removal

1. Defuel helicopter per § 12-42.
2. Turn battery & avionics switches off and pull PRESS. FUELING circuit breaker (5 amp) at circuit breaker panel.
3. Remove tailcone cowling per § 53-23.
4. Refer to Figure 28-8. Open (main) fueling port door. Cut and discard ty-raps as required and disconnect A521 & D745-7 switch assembly wire harnesses from G991-1 harness assembly at connectors.
5. Using appropriate pin extractor, extract pins from switch assembly wire harness connectors; pull grommet and wires thru G257-1 shield.
6. Carefully pull A521 switch assembly wires through grommet, taking care not to damage other wire insulation or grommet.
7. Remove ty-rap as required, and remove screws securing G989-7 shield to F250 cover assembly. Remove shield.
8. Remove fuel cap. Carefully capture A521-6 (single) or A521-7 (dual) switch assembly body with gloved hand.
9. Remove nut securing switch assembly to F250 cover assembly; carefully route wires thru (switch) opening, inside bladder.
10. Carefully pull switch assembly through (fuel cap) opening, avoiding fuel sender. Install fuel cap and protect F250 cover assembly opening.

28-61 A521 (Fuel Level) Switch Assemblies (continued)**C. Installation**

1. Lubricate (new) MS29512-05 packing with A257-6 grease and install packing over A521-6 (single) or A521-7 (dual) switch assembly threads.
2. Refer to Figure 28-8. Open (main) fueling port door and remove fuel cap. With gloved hand, route switch assembly and wiring through (fuel cap) opening inside of bladder. Route wires thru switch assembly opening and install nut securing switch assembly to F250 cover assembly. Special torque nut per § 20-33 and torque stripe per Figure 5-1.
3. Install B266-8 sleeving over switch assembly wires, as required.
4. Carefully pull A521 switch assembly wires through grommet, taking care not to damage other wire insulation or grommet.
5. Pull A521 & D745-7 switch assembly wires and grommet thru G257-1 shield and install grommet.
6. As required, install pins on wires per the following: strip 0.18-inch insulation from wires. Crimp M39029/58-360 pin onto each wire. Using 10X magnification, inspect crimps per § 20-94. Verify no nicked or broken conductors (wire strands), and no insulation damage. As required, gently pry locking lance with fingernail so lance protrudes (lance will not lock in housing unless it protrudes).
7. Install wires in housings per schematic (see Part A). Connect switch assembly wire harnesses to airframe harness at connectors; verify security.
8. Secure switch assembly wiring to G989-7 shield using MS3367-4-0 ty-rap (locate head under shield); lock D269 plug and receptacle and secure to wiring using MS3367-4-9 ty-rap; install MS3397-4-X ty-raps as required to secure wiring. Cinch ty-raps until snug without overtightening and trim tips flush with heads.
9. Apply A257-9 anti-seize to screw threads and install screws securing G989-7 shield to F250 cover assembly.
10. Close (main) fueling port door. Install tailcone cowling per § 53-23.

D. Operation Check

1. Defuel helicopter per § 12-42, as required.
2. Push in PRESS. FUELING circuit breaker (5 amp) at circuit breaker panel. Turn battery switch on.
3. Remove main tank fuel cap. Carefully capture A521-6 (single) or A521-7 (dual) switch assembly float with gloved hand. Have a second person turn on power and set quantity to 25 GAL at pressure fueling control panel; verify VALVE OPEN light is illuminated. Verify light extinguishes when actuating each float individually.
4. Turn off power at pressure fueling control panel. Turn battery switch off.

67-12 Cyclic Grip Assembly (continued)**B. Installation**

1. Refer to Figure 67-1. Ensure protective sleeving covers wires exiting grip assembly with one grommet in grip and one (for cyclic stick) on wire bundle (spare grommets may be installed if desired).
2. Slide grip assembly into bearings in stick assembly. Install washer, castellated nut and cotter pin.

CAUTION

Tighten castellated nut only until there is no axial movement of bearings and cyclic grip assembly. Overtightening nut will damage bearings.

3. Install D684-1 spring so that when grip assembly is rotated one turn clockwise, with co-pilot grip removed, pilot grip (tube) will float just above horizontal and stay full-up when placed full-up. Install circular plug.
4. Temporarily attach grip assembly wiring to safety wire (or lacing) exiting atop cyclic stick. Carefully pull wires thru cyclic stick. Install grommet, included with grip assembly wiring, into cyclic stick wiring entrance hole. Remove safety wire (or lacing).
5. Position protective sleeving on wiring exiting cyclic stick bottom to cover maximum amount of wiring possible. Secure sleeving ends with lacing tape.
6. Install pins on each wire into proper position in housings. Refer to Figure 98-5 | for pin positions.
7. Connect cyclic and airframe wiring at connectors and secure using ty-raps. Cinch | ty-raps until snug without over-tightening, and trim tips flush with heads. Move cyclic control through all positions and verify clearance and no binding.
8. Turn BATTERY switch on and verify correct function of all switches on grip assembly and cyclic stick.
9. Install forward belly panel.

67-13 Cyclic Friction Assembly**NOTE**

The cyclic friction assembly is located below the forward left corner of the cyclic box. Turning friction knob clockwise applies friction to both longitudinal and lateral cyclic axes. Adjustment is required if friction cannot be applied.

A. Friction Adjustment

1. Turn friction knob counter-clockwise until it stops.
2. Remove roll pin connecting knob to shaft.
3. Lift knob off shaft.
4. Install NAS1149F0432P or NAS1149F0463P washers under knob washer, as required, so knob rotates 1/8 to 1 turn before adding friction. With friction off, force at grip to move cyclic shall not exceed 1.75 pounds longitudinal and lateral within hydraulic servo deadbands.
5. Replace knob and install roll pin.
6. Move flight controls throughout complete travel. Verify no binding.

67-20 Collective Control67-21 Collective Stick Assembly**A. Removal**

1. Refer to Figure 67-1. Disconnect A333-1 collective-travel stop from F348-1 anchor by removing NAS6603 bolt at bottom of stop. Position stop parallel to collective stick and apply collective friction.
2. Refer to Figure 6-8. Remove F445-1 forward tunnel cover, F680-3 pilot's collective cover, F680-1 co-pilot's collective cover, F463-1 mid-tunnel cover, and F461-1 collective cross tube cover.

CAUTION

If Garmin FCS is installed in the helicopter, do not allow G356-1 transducer assembly's cable to snap back when disconnecting C522-10 throttle control. Transducer cable must retract slowly; allowing cable to freely retract can damage transducer.

3. Pivot pilot's seat bottom to the open position. Remove bolt securing inboard end of collective stick to pilot's seat structure. Refer to Figures 76-1 and 22-6. Disconnect throttle control inner wire from A462-4 fitting at outboard end of collective. Remove three screws securing C522-10 throttle control (and G356-1 transducer assembly's cable, if installed) to collective cross tube.

67-21 Collective Stick Assembly (continued)**A. Removal (continued)**

4. Disconnect wiring exiting aft end of center collective stick from airframe harness connector. Remove ty-raps as required.
5. Disconnect forward end of F121-1 push-pull tube from collective stick assembly.
6. Remove bolt securing outboard end of collective stick to F303-1 support. Remove two remaining screws securing F303-1 support to cabin. Slide support, with attached micro-switches, down to allow aft movement of collective stick.
7. Pivot pilot's seat bottom to the open position. Remove bolt securing collective stick assembly to pilot's seat structure.
8. Carefully move collective stick assembly aft and remove from helicopter.

B. Installation

1. Refer to Figure 67-1. Position A333-1 collective-travel stop parallel to collective stick and apply collective friction. From aft side of co-pilot's seat, carefully position collective stick assembly in helicopter.
2. Pivot pilot's seat bottom to the open position. Install bolt from inside pilot's seat structure thru bearing block into tunnel and secure to inboard end of collective stick assembly. Standard torque bolt, install stamped nut, and torque stripe per Figure 5-1.
3. At outboard end of collective stick, slide F303-1 support, and attached micro-switches, up behind collective cross tube and secure support to cabin with two screws.
4. Install journal in outboard pivot bearing of collective stick assembly. Position journal & bearing between flanges of F303-1 support and insert NAS6604 bolt. Standard torque bolt per § 20-32, install stamped nut, and torque stripe per Figure 5-1.
5. Connect forward end of F121-1 push-pull tube to collective stick assembly with NAS6604-9 bolt head facing right side of helicopter. Standard torque bolt per § 20-32, install stamped nut, and torque stripe per Figure 5-1.
6. Slide F680-3 collective cover over pilot collective stick aft of friction assembly.
7. Insert A130-4 spacer into lower end of A333-1 collective-travel stop. Position spacer and stop in F348-1 anchor. Install NAS1149F0432P and 0463P washers on spacer on either side of stop as required to obtain 0.001/0.035 inch axial play and align stop with collective. Secure stop to anchor with NAS6603 bolt, standard torque per § 20-32, install stamped nut, and torque stripe per Figure 5-1. Move collective up & down and verify no binding of stop.
8. Connect wiring exiting center collective stick to airframe wire harness connector. Secure connector to airframe harness with Ty-raps as required. Move collective up & down and verify wiring clearance with no strain.

67-21 Collective Stick Assembly (continued)**B. Installation (continued)**

9. Refer to Figure 76-1. Secure C522-10 throttle control to collective stick weldment with three clamps and screws. If Garmin FCS is installed in helicopter, secure G356-1 transducer assembly's cable to collective per Figure 22-6 and perform collective position sensor calibration per § 22-16-2 Part B. Position throttle control inner wire in A462-4 fitting and rig per § 76-11.
10. Refer to Figure 6-8. Install and secure F445-1 forward tunnel cover, F680-3 pilot's collective cover, F680-1 co-pilot's collective cover, F463-1 mid-tunnel cover, and F461-1 collective cross tube cover.
11. Adjust collective friction per § 67-22.

67-22 Collective Friction

Adjust friction on F334-1 to produce a force within servo dead bands of 4–5 lb when pulling up at collective grip with friction on collective full off, then adjust friction on collective as required to produce a force of 18–22 lb when pulling up at grip when full on.

67-30 Jackshaft and Strut Assembly67-31 Jackshaft**A. Removal****NOTE**

Rigging check is not necessary if jackshaft support rod end and push-pull tube lengths are not altered.

1. Disconnect push-pull tubes from F339-1 jackshaft.
2. Disconnect two bolts connecting jackshaft to G201-1 frame.
3. Remove jackshaft.

B. Installation

1. Ensure A105-6 journal is installed in jackshaft aft support on G201-1 frame. Position F339-1 jackshaft on G201-1 frame and install bolts. Standard torque bolts per § 20-32, install stamped nuts, and torque stripe per Figure 5-1.
2. Insert bolt forward thru forward jackshaft arm and connect to upper end of F121-7 push-pull tube. Install A115-1 spacer, A214-3 washer and nut. Standard torque bolt per § 20-32, install stamped nut, and torque stripe per Figure 5-1.
3. Insert bolt aft thru aft jackshaft arm and connect to lower rod end on C343-8 tube. Install A115-1 spacer, A214-3 washer and nut. Standard torque bolt per § 20-32, install stamped nut, and torque stripe per Figure 5-1.
4. Verify no binding and/no interference with control system exists throughout flight control travel.

76-11 FCU Throttle Control Rigging

1. Remove engine cowling assembly per § 53-21. Remove F461-1 collective cross tube cover and (copilot) F680-1 collective cover assembly (refer to § 6-70).
2. Refer to Figure 76-1. Verify FCU throttle lever rigging angle is $48.5^\circ \pm 7.5^\circ$. As required, remove hardware securing serrated levers and reposition to proper angle. Install hardware, special torque nut per § 20-33, & torque stripe per Figure 5-1.
3. Remove stamped nuts and loosen nuts securing A462-4 fittings and C522-10 (throttle) control inner wire to collective arm and to FCU throttle lever.
4. Position forward end of control housing flush—0.25 inch at or beyond edge of outboard AN742-3 clamp and install fasteners securing housing and clamps to F764-1 collective stick weldment.
5. Refer to detail in Figure 76-3. Rotate collective stick twist grip open. Position inner wire 0.10–0.30 inch beyond outboard edge of fitting in collective arm, and special torque fitting nut per § 20-33. Install stamped nut, standard torque per § 20-32, & torque stripe per Figure 5-1.
6. Position aft end of control housing 1.10–1.30 inches beyond edge of aft AN742-4 clamp and install fasteners securing housing and clamps to F577-3 bracket.
7. Refer to detail in Figure 76-3. Rotate twist grip closed; rotate and hold FCU throttle lever to contact idle stop. Verify sufficient inner wire beyond aft edge of fitting, and special torque fitting nut per § 20-33.
8. Rotate twist grip open; verify FCU throttle lever contacts maximum throttle stop, and 0.030–0.050 inch gap between F328-1 connecting rod and throttle stop washer. Reposition fitting on wire as required until proper rod-to-washer gap, and FCU throttle lever contacts maximum throttle stop with twist grip open, and idle stop with twist grip closed.
9. Install fitting stamped nut, standard torque per § 20-32, and torque stripe per Figure 5-1. Trim control wire 0.10–0.30 inch beyond aft edge of fitting.
10. Install collective cross tube cover and collective cover assembly. As required, perform: FCU fuel cutoff control rigging per § 76-12; or install engine cowling assembly per § 53-21; or collective position sensor calibration per § 22-16-2 Part B (if Garmin FCS is installed).

76-12 FCU Fuel Cutoff Control Rigging

1. Remove engine cowling assembly per § 53-21.
2. Refer to Figure 76-1. Remove stamped nut and loosen nut securing A462-4 fitting and A522-10 (fuel cutoff) control inner wire to FCU fuel cutoff lever.
3. Rotate FCU fuel cutoff lever into OFF detent; pull fuel cutoff control knob OFF (at lower console). Position end of control housing flush—0.050 inch from forward edge of fitting and install fasteners securing housing and AN742-4 clamps to F577-1 bracket assembly.
4. Refer to details in Figure 76-3. Verify sufficient inner wire beyond aft edge of fitting, and special torque fitting nut per § 20-33.




FIGURE 76-2 POWER TURBINE GOVERNOR

CHAPTER 95

INSTRUMENT SYSTEM

<u>Section</u>	<u>Title</u>	<u>Page</u>
95-00	Description	95.1
95-10	Pitot-Static System	95.3
95-20	Primary Instruments	95.5
95-21	Vertical Speed Indicator	95.6
95-22	Airspeed Indicator	95.7
95-23	Engine (N ₂) and Rotor Dual Tachometer	95.8
95-24	Altimeter	95.11
95-25	Torquemeter	95.12
95-26	Magnetic Compass	95.13
95-30	Engine Gages	95.14
95-31	N ₁ Tachometer	95.14
95-32	Measured Gas (Turbine) Temperature (MGT) Gage	95.15
95-33	Engine Oil Pressure Gage	95.16
95-34	Engine Oil Temperature Gage	95.16
95-35	Fuel Quantity Gage	95.17
95-40	Additional Standard Indicating Equipment	95.18
95-41	Clock	95.18
95-42	Ammeter	95.19
95-43	Outside Air Temperature (OAT) Gage/Voltmeter	95.20
95-44	Hourmeters	95.21
95-50	Console Assemblies	95.22
95-60	Instrument Markings	95.22
95-70	Electronic Flight Displays	95.25
95-71	Garmin Display Unit (GDU) 700L TXi or 1060 TXi	95.25
95-72	Garmin Display Unit (GDU) 620	95.27
95-73	Aspen EFD500H & EFD1000H Display(s) Installation	95.28

Intentionally Blank

Intentionally Blank




FIGURE 95-4 GARMIN G500H UPPER CONSOLE (GDU 1060 SHOWN)




FIGURE 95-5 GARMIN G500H UPPER CONSOLE PITOT-STATIC SCHEMATIC

95-70 Electronic Flight Displays

95-71 Garmin Display Unit (GDU) 700L TXi or 1060 TXi

NOTE

Refer to Garmin G500H Instructions for Continued Airworthiness.

A. Description

The GDU 700L TXi or 1060 TXi is integrated with the Garmin G500H Electronic Flight Instrument System (EFIS). GDU 700L & 1060 electronically displays primary flight instrumentation via a primary flight display (PFD), and moving map, weather, traffic, terrain, and other functionality via a multifunction display (MFD) that includes touch-screen technology on one 7 inch (700L) or 10.6 inch (1060) display.

Refer to § 97-10 for Garmin G500H EFIS system components.

B. Schematics

Refer to Figure 98-9 for GDU 700L/1060 installation electrical schematic.

Refer to Figures 95-3 & 95-5 for Garmin G500H upper console pitot-static schematic.

C. Removal

1. Turn battery & avionics switches off and pull out EFIS circuit breaker (5 amp) on circuit breaker panel.
2. Remove screws securing GDU to console face.
3. Pull out and support display, unplug console harness connectors, and remove display.

D. Installation

1. Turn battery & avionics switches off and pull out EFIS circuit breaker (5 amp) on circuit breaker panel.
2. Visually inspect console harness connectors and verify no bent or damaged pins. Support display and plug in console harness connectors.
3. Place GDU in console, then install and tighten screws. Verify security.
4. Push in EFIS circuit breaker on circuit breaker panel. Turn battery & avionics switches on.
5. Perform appropriate functional checks per Garmin G500H Instructions for Continued Airworthiness. Turn battery & avionics switches off.

95-71 Garmin Display Unit (GDU) 700L TXi or 1060 TXi (continued)

E. Pitch/Roll Offset Calibration

NOTE

A Garmin Installer Unlock card is required to perform this procedure.

NOTE

All factory-installed Garmin units are configured to each helicopter. Perform only the steps outlined in this procedure without making additional changes.

1. Ensure GDU is off, then insert Garmin's Installer Unlock card in lower/left slot.
2. Press and hold right-inner knob, then press and release power button. After screen turns on, release right-inner knob.
3. Ensure external LRUs are online, indicated by green boxes on left side of display.
4. Press *Attitude/Heading, Calibration/Test*.
5. Select **Pitch/Roll Offset** procedure.
6. Follow and confirm each on-screen instruction.

NOTE

Verify aircraft is positioned on skids on level ground.

7. Press **Calibrate** and confirm successful calibration.
8. Press **Close**, power off GDU, then remove Installer Unlock card.

F. Magnetometer Calibration

NOTE

This procedure must be performed during a flight check.

NOTE

A Garmin Installer Unlock card is required to perform this procedure.

NOTE

All factory-installed Garmin units are configured to each helicopter. Perform only the steps outlined in this procedure without making additional changes.

95-71 Garmin Display Unit (GDU) 700L TXi or 1060 TXi (continued)**F. Magnetometer Calibration (continued)**

NOTE

If helicopter has Garmin GFC 600H Helicopter Flight Control System (FCS) installed, refer to § 22-16-2 Part D and perform FCS and GDU magnetometer calibration simultaneously.

1. If not previously accomplished, perform Pitch/Roll Offset Calibration per Part E.
2. Ensure GDU is off, then insert Garmin's Installer Unlock card in lower/left slot.
3. Press and hold right-inner knob, then press and release power button. After screen turns on, release right-inner knob.
4. Ensure external LRUs are online, indicated by green boxes on left side of display.
5. Press *Attitude/Heading, Calibration/Test*.
6. Select **Magnetometer** procedure.
7. Read thru on-screen checklist and confirm each instruction.
8. Press **Calibrate**.
9. With appropriately rated person at controls, start helicopter. Follow on-screen procedure until **Calibration Successful** is displayed, then press close to exit.
10. Have pilot land the helicopter. Press and hold power button to power off, then remove the Installer Unlock card.
11. Press power button to power on GDU in normal mode. Have pilot rotate helicopter and verify alignment with analog compass.
12. Have pilot complete flight check if required, or land and shut down helicopter.

95-71 Garmin Display Unit (GDU) 700L TXi or 1060 TXi (continued)**G. Scheduled Maintenance and Inspections**

Refer to Garmin G500H Instructions for Continued Airworthiness.

NOTE

All factory-installed Garmin units are “on condition” and do not require scheduled periodic maintenance. Units feature a BIT (Built-In Test) function during each initial power-up that will detect internal failure(s) and alert pilot.

NOTE

Refer to § 97-60 for avionics software information.

H. Special Maintenance and Inspections

1. Remove GDU per Part C.
2. Open circuit breaker panel and upper console.
3. Inspect condition of and verify no obvious damage to GDU, copper bus bars, circuit breaker, and wiring. Verify no loose, chafed, or broken wires or terminals. Verify no evidence of arcing. Verify installed equipment security.
4. Secure circuit breaker panel and upper console.
5. Install GDU per Part D.

Intentionally Blank




FIGURE 95-6 GARMIN G500H UPPER CONSOLE WITH GDU 620

95-72 Garmin Display Unit (GDU) 620 Installation**NOTE**

Refer to Garmin G500H Instructions for Continued Airworthiness.

A. Description

The GDU 620 integrates with the Garmin G500H Electronic Flight Instrument System (EFIS). The GDU 620 electronically displays primary flight instrumentation via a primary flight display (PFD), and moving map, weather, traffic, terrain and other functionality via a multifunction display (MFD) on dual 6.5 inch displays.

Refer to § 97-10 for Garmin G500H EFIS system components.

B. Schematics

Refer to Figure 98-10 for GDU 620 installation electrical schematic.

Refer to Figures 95-3 & 95-5 for Garmin G500H upper console pitot-static schematic.

C. Removal

1. Turn battery & avionics switches off and pull out EFIS circuit breaker (5 amp) on circuit breaker panel.
2. Remove screws securing GDU to console face.
3. Pull out and support display, unplug console harness connectors, and remove display.

D. Installation

1. Turn battery & avionics switches off and pull out EFIS circuit breaker (5 amp) on circuit breaker panel.
2. Visually inspect console harness connectors and verify no bent or damaged pins. Support display and plug in console harness connectors.
3. Place GDU in console, then install and tighten screws. Verify security.
4. Push in EFIS circuit breaker on circuit breaker panel. Turn battery & avionics switches on.
5. Perform appropriate functional checks per Garmin G500H Instructions for Continued Airworthiness. Turn battery & avionics switches off.

E. Scheduled Maintenance and Inspections

Refer to Garmin G500H Instructions for Continued Airworthiness.

F. Special Maintenance and Inspections

Refer to § 95-71 Part F.




FIGURE 95-7 EIGHT-INSTRUMENT CONSOLE WITH ASPEN PFD




FIGURE 95-8 EIGHT-INSTRUMENT CONSOLE WITH ASPEN PFD PITOT-STATIC SCHEMATIC

95-73 Aspen EFD500H & EFD1000H Display(s) Installation

A. Description

R66 options include a single screen Aspen PFD, or a dual-screen Aspen PFD and MFD.

The Aspen PFD (Primary Flight Display) is an LCD unit with displays for attitude, altitude, airspeed, heading, and optional NAV (HSI/CDI). The Aspen PFD is a situational awareness aid, to be used in conjunction with required VFR instruments (altimeter, airspeed indicator, and magnetic compass).

The standard Aspen PFD installation configures the lower half of the display as a directional gyro. An optional installation configures the lower half of the display to a Horizontal Situation Indicator (HSI). Primary GPS position data is provided by GTN-series GPS. Heading and outside air temperature data is received from the Aspen remote sensor module (RSM). The RSM provides backup GPS position data if primary GPS fails.

The Aspen MFD (Multifunction Display) is an LCD unit with displays for moving map navigation data, terrain, and traffic. Terrain and traffic may also be overlaid on moving map. GPS position data is provided by Garmin GTN-series GPS for moving map and terrain displays. Aspen MFD also includes an internal terrain database. TIS-A traffic data may be received from Garmin GTX330 transponder for moving map display.




FIGURE 95-9 SIX-INSTRUMENT CONSOLE WITH ASPEN PFD PITOT-STATIC SCHEMATIC




FIGURE 95-10 EIGHT-INSTRUMENT CONSOLE WITH ASPEN PFD AND MFD




FIGURE 95-11 EIGHT-INSTRUMENT CONSOLE WITH ASPEN PFD AND MFD PITOT-STATIC SCHEMATIC

CHAPTER 98

WIRING DIAGRAMS

<i>Figure</i>	<i>Title</i>	<i>Page</i>
98-1	R66 Electrical System (F024-2 Revision X)	98.1
98-1A	R66 Electrical System (F024-2 Revision V)	98.2
98-2A	R66 Electrical System (F024-2 Revision R)	98.2A
98-2B	R66 Electrical System (F024-1 Revision J)	98.2B
98-3	Air Conditioning Installation	98.3
98-4	ADF Installation	98.5
98-5	Standard Audio Installation (NAT AA12S-600 Audio Control)	98.7
98-6	Dual Audio Control Installation	98.9
98-7	PA/Siren Installation	98.11
98-8A	Garmin Flight Control System (FCS) Installation	98.13
98-8B	HeliSAS – Autopilot Installation	98.13B
98-8C	HeliSAS – Autopilot Installation	98.14
98-9	Garmin GDU 1060 Installation	98.15
98-9A	Garmin GDU 620 Installation	98.16
98-10	Garmin GSU 75 ADAHRS Installation	98.17
98-11	Garmin GDC 74H Air Data Computer Installation	98.19
98-12	Garmin GRS 77H AHRS Installation	98.21
98-13	Garmin GTN 6XX/7XX-series GPS Installation (G500H EFIS)	98.23
98-13A	Avidyne IFD 4XX/5XX-series GPS Installation	98.24A
98-13B	Garmin 500 Series GPS Installation	98.24C
98-13C	Garmin 500 Series GPS Installation	98.24D
98-14	Radar Altimeter Installation	98.25
98-15	Garmin GTX 3X5 Transponder Installation	98.27
98-16	Garmin GTX 33/328/330 ES Transponder Installation	98.29
98-17	Garmin GDL 69A XM Receiver Installation	98.31
98-18	Aspen EFD1000H Display Installation	98.33
98-19	Aspen EFD500H Display Installation	98.35
98-20	Garmin GTR 225B / GNC 225B NAV/COM Radio Installation	98.37
98-21	Garmin GTR 225B COM Radio Installation	98.39
98-22	Garmin GDL 88 ADS-B In Receiver Installation	98.41
98-23	Garmin GTN 6XX/7XX-series GPS Installation (Pilot-Side Console)	98.43
98-24	F060 Intercom System Installation (Garmin GMA 350HC Audio Control) . . .	98.45
98-25A	F060-4, -5, -6 & -7 Intercom System Installation (Garmin GMA 350HC Audio Control)	98.45B

CHAPTER 98

WIRING DIAGRAMS (Continued)

<i>Figure</i>	<i>Title</i>	<i>Page</i>
98-25B	F060-1 & -2 Intercom System Installation (Garmin GMA 350H Audio Control)	98.46
98-26	Lithium-Ion Battery Installation	98.47
98-27	Heated Seats Installation	98.51
98-28	Cargo Hook Installation	98.53
98-29	External Load Controls	98.55
98-30	Copilot Instruments Installation	98.57
98-31	Bubble Door Fans Installation	98.59
98-32	Dual Low Fuel Warning Light Installation	98.61
98-33	Fuel Flow Meter Installation	98.61
98-34	Pressure Fueling System Installation	98.63




FIGURE 98-8A GARMIN FLIGHT CONTROL SYSTEM (FCS) INSTALLATION

G325 REV D

Intentionally Blank




FIGURE 98-8B D325-1 AUTOPILOT (HELISAS, WITHOUT BC MODE) SCHEMATIC





FIGURE 98-8C D325-1 AUTOPILOT (HELISAS, WITH BC MODE) SCHEMATIC



G986 REV D

2X B263-12/-13

FIGURE 98-34 PRESSURE FUELING SYSTEM INSTALLATION (OPTIONAL)

Intentionally Blank

CHAPTER 99
SPECIAL TOOLS

99-10 Special Tools

The following is a list of Robinson R66 special tools.

R66 special tools are to be used in conjunction with the applicable instructions for continued airworthiness, for their designated maintenance task.

99-20 Illustrations and Tasks

Refer to Figure 99-1.

Item	Part Number	Description
1	MT054-1	Main Gearbox Drain Assembly
2	MT107-1	Socket (Pressure Fueling Valve)
3	MT122-6	Micrometer Assembly – Main Rotor Hub, Bolt Stretch
4	MT146-4	Blocks – Swashplate Rigging (set of 2)
5	MT147-1	Bleed Tool – Main Rotor Blade Spindle [includes (2) MT147-2 fittings]
6	MT179-4	Balancing Bar – Tail Rotor Assembly Static Balance
7	MT260-6	Tail Rotor Drive Shaft Runout Attachments Kit
8	MT329-6	Plug – Main Rotor Hub Bearing Installation/Removal
9	MT329-10	Tube – Main Rotor Hub Bearing Removal




FIGURE 99-1 SPECIAL TOOLS

REVISION LOG

MAR 2026

The R66 Maintenance Manual (MM) list of effective pages and effective dates are given below. If a previously issued page is not listed below, it is no longer an effective page and must be discarded. The issue or revision date is in bold at the top of each revision log page.

Please visit <https://robinsonheli.com> to verify the issue or revision date is current.

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
i	MAR 2026	4.2	JUL 2023	5.21A	MAR 2025
ii	MAR 2026	4.3	SEP 2024	5.21B	MAR 2025
iii	JUL 2020	4.4	SEP 2024	5.21C	MAR 2025
iv	JUL 2020			5.21D	MAR 2025
v	APR 2017	5.i	MAR 2025	5.22	MAR 2025
vi	APR 2017	5.ii	MAR 2025	5.23	MAY 2021
		5.1	MAR 2025	5.24	MAY 2021
1.i	JUL 2023	5.2	MAR 2025	5.25	APR 2019
1.ii	JUL 2023	5.3	JUL 2023	5.26	APR 2019
1.1	APR 2019	5.4	JUL 2023	5.27	JUL 2023
1.2	APR 2019	5.5	MAY 2021	5.28	JUL 2023
1.3	JUL 2023	5.6	MAY 2021	5.28A	MAR 2025
1.4	JUL 2023	5.7	JUL 2020	5.28B	MAR 2025
1.4A	JUL 2023	5.8	JUL 2020	5.29	MAR 2025
1.4B	JUL 2023	5.9	JUL 2020	5.30	MAR 2025
1.5	SEP 2012	5.9A	JUL 2020	5.31	JUL 2023
1.6	SEP 2012	5.9B	JUL 2020	5.32	JUL 2023
1.7	SEP 2023	5.10	JUL 2020	5.33	JUL 2023
1.8	SEP 2023	5.11	NOV 2023	5.34	JUL 2023
1.9	MAR 2025	5.12	NOV 2023	5.34A	MAY 2021
1.10	MAR 2025	5.13	MAR 2025	5.34B	MAY 2021
1.11	JUL 2020	5.14	MAR 2025	5.35	JUL 2023
1.12	JUL 2020	5.15	MAY 2021	5.36	JUL 2023
1.13	MAR 2026	5.16	MAY 2021	5.37	MAY 2021
1.14	MAR 2026	5.16A	MAR 2026	5.38	MAY 2021
1.15	MAR 2026	5.16B	MAR 2026	5.38A	MAY 2021
1.16	MAR 2026	5.17	MAR 2026	5.38B	MAY 2021
1.17	JUL 2020	5.18	MAR 2026	5.39	JUL 2023
1.18	JUL 2020	5.19	JUL 2020	5.39A	JUL 2023
		5.20	JUL 2020	5.39B	JUL 2020
4.i	SEP 2023	5.20A	JUL 2023	5.39C	JUL 2020
4.ii	SEP 2023	5.20B	JUL 2023	5.39D	JUL 2020
4.1	JUL 2023	5.21	MAR 2025	5.40	JUL 2020

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
5.41	SEP 2023				
5.42	SEP 2023	8.i	SEP 2023	12.i	JUL 2020
5.43	MAY 2015	8.ii	SEP 2023	12.ii	JUL 2020
5.44	MAY 2015	8.1	SEP 2012	12.1	SEP 2012
5.45	APR 2019	8.2	SEP 2012	12.2	SEP 2012
5.46	APR 2019	8.3	SEP 2012	12.3	APR 2019
5.47	APR 2019	8.4	SEP 2012	12.4	APR 2019
5.47A	APR 2019	8.5	25 OCT 2010	12.5	SEP 2012
5.47B	APR 2017	8.6	25 OCT 2010	12.6	SEP 2012
5.48	APR 2017	8.7	MAR 2025	12.7	SEP 2012
5.49	MAY 2021	8.8	MAR 2025	12.8	SEP 2012
5.50	MAY 2021	8.9	MAR 2025	12.9	MAY 2021
5.51	MAR 2025	8.10	MAR 2025	12.10	MAY 2021
5.52	MAR 2025	8.11	SEP 2023	12.11	SEP 2012
		8.12	SEP 2023	12.12	SEP 2012
6.i	SEP 2023	8.13	NOV 2023	12.13	JUL 2023
6.ii	SEP 2023	8.14	NOV 2023	12.13A	JUL 2023
6.1	SEP 2023			12.13B	APR 2017
6.2	SEP 2023	9.i	25 OCT 2010	12.14	APR 2017
6.3	SEP 2023	9.ii	25 OCT 2010	12.15	MAR 2025
6.4	SEP 2023	9.1	25 OCT 2010	12.16	MAR 2025
6.5	25 OCT 2010	9.2	25 OCT 2010	12.17	JUL 2020
6.6	25 OCT 2010	9.3	SEP 2012	12.17A	JUL 2020
6.7	SEP 2023	9.4	SEP 2012	12.17B	JUL 2020
6.8	SEP 2023			12.18	JUL 2020
6.9	SEP 2023	10.i	25 OCT 2010	12.19	JUL 2023
6.10	SEP 2023	10.ii	25 OCT 2010	12.20	JUL 2023
6.11	SEP 2023	10.1	SEP 2023	12.21	JUL 2023
6.12	SEP 2023	10.2	SEP 2023	12.22	JUL 2023
		10.3	SEP 2023		
7.i	25 OCT 2010	10.4	SEP 2023	18.i	JUL 2023
7.ii	25 OCT 2010	10.5	25 OCT 2010	18.ii	JUL 2023
7.1	SEP 2012	10.6	25 OCT 2010	18.1	SEP 2023
7.2	SEP 2012			18.2	SEP 2023
7.3	SEP 2012	11.i	APR 2017	18.3	JUL 2023
7.4	SEP 2012	11.ii	APR 2017	18.4	JUL 2023
7.5	25 OCT 2010	11.1	MAY 2021	18.5	SEP 2023
7.6	25 OCT 2010	11.2	MAY 2021	18.6	SEP 2023

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
18.7	SEP 2023	18.37	JUL 2023	20.16	JUL 2023
18.7A	SEP 2023	18.38	JUL 2023	20.17	JUL 2023
18.7B	APR 2017			20.18	JUL 2023
18.7C	APR 2017	20.i	JUL 2023	20.18A	SEP 2023
18.7D	APR 2017	20.ii	JUL 2023	20.18B	SEP 2023
18.8	APR 2017	20.1	JUL 2023	20.19	JUL 2023
18.9	APR 2017	20.2	JUL 2023	20.20	JUL 2023
18.10	APR 2017	20.2A	JUL 2023	20.21	JUL 2020
18.10A	APR 2017	20.2B	JUL 2023	20.22	JUL 2020
18.10B	APR 2017	20.3	JUL 2023	20.23	MAY 2021
18.11	25 OCT 2010	20.4	JUL 2023	20.24	MAY 2021
18.12	25 OCT 2010	20.5	JUL 2023	20.25	APR 2017
18.13	25 OCT 2010	20.6	JUL 2023	20.26	APR 2017
18.14	25 OCT 2010	20.7	SEP 2023		
18.15	SEP 2023	20.8	SEP 2023	21.i	SEP 2012
18.16	SEP 2023	20.9	SEP 2023	21.ii	SEP 2012
18.17	SEP 2023	20.10	SEP 2023	21.1	MAY 2015
18.18	SEP 2023	20.10A	JUL 2023	21.2	MAY 2015
18.19	JUL 2023	20.10B	JUL 2023	21.3	SEP 2012
18.20	JUL 2023	20.11	JUL 2023	21.4	SEP 2012
18.21	JUL 2023	20.11A	JUL 2023	21.5	MAY 2015
18.21A	JUL 2023	20.11B	JUL 2020	21.6	MAY 2015
18.21B	JUL 2023	20.11C	JUL 2020	21.7	SEP 2012
18.22	JUL 2023	20.11D	JUL 2020	21.8	SEP 2012
18.23	JUL 2023	20.11E	JUL 2020	21.9	JUL 2020
18.24	JUL 2023	20.11F	JUL 2020	21.10	JUL 2020
18.25	JUL 2023	20.11G	JUL 2020	21.11	SEP 2012
18.26	JUL 2023	20.11H	JUL 2020	21.12	SEP 2012
18.27	MAY 2015	20.11I	JUL 2020	21.13	SEP 2012
18.28	MAY 2015	20.11J	JUL 2020	21.14	SEP 2012
18.29	JUL 2023	20.11K	JUL 2020		
18.30	JUL 2023	20.11L	JUL 2020	22.i	MAR 2026
18.31	MAY 2015	20.11M	JUL 2020	22.ii	MAR 2026
18.32	MAY 2015	20.11N	JUL 2020	22.1	MAR 2026
18.33	JUL 2023	20.12	JUL 2020	22.2	MAR 2026
18.34	JUL 2023	20.13	JUL 2023	22.3	MAR 2026
18.35	JUL 2023	20.14	JUL 2023	22.4	MAR 2026
18.36	JUL 2023	20.15	JUL 2023	22.5	MAR 2026

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
22.6	MAR 2026	22.44	MAR 2026	25.11	APR 2019
22.7	MAR 2026	22.45	MAR 2026	25.12	APR 2019
22.8	MAR 2026	22.46	MAR 2026	25.13	MAY 2021
22.9	MAR 2026	22.47	MAR 2026	25.14	MAY 2021
22.10	MAR 2026	22.48	MAR 2026	25.15	APR 2019
22.11	MAR 2026	22.49	MAR 2026	25.16	APR 2019
22.12	MAR 2026	22.50	MAR 2026	25.17	JUL 2023
22.13	MAR 2026	22.51	MAR 2026	25.18	JUL 2023
22.14	MAR 2026	22.52	MAR 2026	25.19	APR 2019
22.15	MAR 2026	22.53	MAR 2026	25.20	APR 2019
22.16	MAR 2026	22.54	MAR 2026	25.21	APR 2019
22.17	MAR 2026	22.55	MAR 2026	25.22	APR 2019
22.18	MAR 2026	22.56	MAR 2026	25.23	APR 2019
22.19	MAR 2026	22.57	MAR 2026	25.24	APR 2019
22.20	MAR 2026	22.58	MAR 2026	25.25	APR 2019
22.21	MAR 2026	22.59	MAR 2026	25.26	APR 2019
22.22	MAR 2026	22.60	MAR 2026	25.27	APR 2019
22.23	MAR 2026	22.61	MAR 2026	25.28	APR 2019
22.24	MAR 2026	22.62	MAR 2026	25.29	APR 2019
22.25	MAR 2026	22.63	MAR 2026	25.30	APR 2019
22.26	MAR 2026	22.64	MAR 2026	25.31	JUL 2023
22.27	MAR 2026	22.65	MAR 2026	25.32	JUL 2023
22.28	MAR 2026	22.66	MAR 2026		
22.29	MAR 2026	22.67	MAR 2026	28.i	JUL 2023
22.30	MAR 2026	22.68	MAR 2026	28.ii	JUL 2023
22.31	MAR 2026			28.1	JUL 2023
22.32	MAR 2026	25.i	JUL 2023	28.2	JUL 2023
22.33	MAR 2026	25.ii	JUL 2023	28.3	APR 2017
22.34	MAR 2026	25.1	JUL 2023	28.4	APR 2017
22.35	MAR 2026	25.2	JUL 2023	28.5	JUL 2020
22.36	MAR 2026	25.3	SEP 2012	28.6	JUL 2020
22.37	MAR 2026	25.4	SEP 2012	28.7	JUL 2020
22.38	MAR 2026	25.5	APR 2019	28.8	JUL 2020
22.39	MAR 2026	25.6	APR 2019	28.9	JUL 2020
22.40	MAR 2026	25.7	APR 2019	28.9A	JUL 2020
22.41	MAR 2026	25.8	APR 2019	28.9B	JUL 2020
22.42	MAR 2026	25.9	APR 2019	28.10	JUL 2020
22.43	MAR 2026	25.10	APR 2019	28.11	JUL 2020

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
28.11A	JUL 2020	29.1	MAR 2025	32.24	SEP 2012
28.11B	JUL 2020	29.2	MAR 2025		
28.11C	JUL 2020	29.3	MAR 2025	33.i	MAY 2015
28.11D	JUL 2020	29.4	MAR 2025	33.ii	MAY 2015
28.12	JUL 2020	29.5	MAR 2025	33.1	SEP 2023
28.13	APR 2017	29.6	MAR 2025	33.2	SEP 2023
28.14	APR 2017	29.7	JUL 2020	33.3	MAY 2015
28.15	JUL 2020	29.8	JUL 2020	33.4	MAY 2015
28.16	JUL 2020	29.9	JUL 2020		
28.17	JUL 2020	29.10	JUL 2020	52.i	JUL 2023
28.18	JUL 2020			52.ii	JUL 2023
28.19	JUL 2020	32.i	SEP 2012	52.1	JUL 2020
28.20	JUL 2020	32.ii	SEP 2012	52.2	JUL 2020
28.21	JUL 2020	32.1	MAY 2015	52.3	JUL 2020
28.22	JUL 2020	32.2	MAY 2015	52.4	JUL 2020
28.23	APR 2019	32.3	APR 2017	52.5	JUL 2023
28.24	APR 2019	32.3A	APR 2017	52.6	JUL 2023
28.25	JUL 2020	32.3B	APR 2017	52.7	25 OCT 2010
28.26	JUL 2020	32.4	APR 2017	52.8	25 OCT 2010
28.27	JUL 2020	32.5	SEP 2012	52.9	JUL 2020
28.28	JUL 2020	32.6	SEP 2012	52.10	JUL 2020
28.29	MAR 2026	32.7	SEP 2012	52.11	JUL 2023
28.30	MAR 2026	32.8	SEP 2012	52.12	JUL 2023
28.31	MAR 2026	32.9	SEP 2023	52.13	JUL 2023
28.32	MAR 2026	32.10	SEP 2023	52.14	JUL 2023
28.33	JUL 2023	32.11	SEP 2012	52.15	JUL 2023
28.34	JUL 2023	32.12	SEP 2012	52.16	JUL 2023
28.35	JUL 2023	32.13	MAY 2021	52.17	JUL 2023
28.36	JUL 2023	32.14	MAY 2021	52.18	JUL 2023
28.37	JUL 2023	32.15	SEP 2012	52.19	JUL 2023
28.38	JUL 2023	32.16	SEP 2012	52.20	JUL 2023
28.39	JUL 2023	32.17	SEP 2012	52.21	JUL 2023
28.40	JUL 2023	32.18	SEP 2012	52.22	JUL 2023
28.41	JUL 2023	32.19	JUL 2023		
28.42	JUL 2023	32.20	JUL 2023	53.i	NOV 2023
		32.21	JUL 2023	53.ii	NOV 2023
29.i	MAY 2015	32.22	JUL 2023	53.1	MAR 2025
29.ii	MAY 2015	32.23	SEP 2012	53.2	MAR 2025

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
53.3	APR 2019	62.8	JUL 2023	63.3	JUL 2020
53.4	APR 2019	62.9	JUL 2023	63.4	JUL 2020
53.5	JUL 2020	62.10	JUL 2023	63.5	JUL 2023
53.6	JUL 2020	62.10A	JUL 2023	63.6	JUL 2023
53.7	JUL 2020	62.10B	JUL 2023	63.7	APR 2017
53.8	JUL 2020	62.11	JUL 2023	63.8	APR 2017
53.9	25 OCT 2010	62.12	JUL 2023	63.9	MAR 2025
53.10	25 OCT 2010	62.13	JUL 2023	63.10	MAR 2025
53.11	MAY 2015	62.14	JUL 2023	63.11	APR 2017
53.12	MAY 2015	62.15	JUL 2023	63.12	APR 2017
53.13	MAR 2025	62.16	JUL 2023	63.13	APR 2017
53.14	MAR 2025	62.17	JUL 2023	63.14	APR 2017
53.15	NOV 2023	62.17A	JUL 2023		
53.16	NOV 2023	62.17B	JUL 2023	64.i	JUL 2023
53.17	NOV 2023	62.17C	JUL 2023	64.ii	JUL 2023
53.18	NOV 2023	62.17D	JUL 2020	64.1	MAR 2025
53.19	MAR 2025	62.18	JUL 2020	64.2	MAR 2025
53.20	MAR 2025	62.19	JUL 2020	64.3	MAR 2025
53.21	MAR 2025	62.20	JUL 2020	64.4	MAR 2025
53.22	MAR 2025	62.21	APR 2019	64.5	JUL 2023
53.23	NOV 2023	62.21A	APR 2019	64.6	JUL 2023
53.24	NOV 2023	62.21B	APR 2019	64.7	JUL 2023
53.25	MAR 2025	62.22	APR 2019	64.8	JUL 2023
53.26	MAR 2025	62.23	APR 2019	64.9	JUL 2023
53.27	NOV 2023	62.24	APR 2019	64.10	JUL 2023
53.28	NOV 2023	62.25	MAY 2021	64.11	JUL 2023
53.29	NOV 2023	62.26	MAY 2021	64.12	JUL 2023
53.30	NOV 2023	62.27	MAR 2025	64.13	JUL 2023
		62.28	MAR 2025	64.14	JUL 2023
62.i	MAR 2025	62.29	MAR 2025	64.15	JUL 2023
62.ii	MAR 2025	62.30	MAR 2025	64.16	JUL 2023
62.1	JUL 2023	62.31	MAR 2025	64.17	JUL 2023
62.2	JUL 2023	62.32	MAR 2025	64.18	JUL 2023
62.3	JUL 2023			64.19	JUL 2023
62.4	JUL 2023	63.i	APR 2017	64.20	JUL 2023
62.5	JUL 2023	63.ii	APR 2017	64.21	JUL 2023
62.6	JUL 2023	63.1	APR 2017	64.22	JUL 2023
62.7	JUL 2023	63.2	APR 2017		

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
65.i	SEP 2012	71.1	JUL 2020	76.5	25 OCT 2010
65.ii	SEP 2012	71.2	JUL 2020	76.6	25 OCT 2010
65.1	MAY 2015	71.3	JUL 2020	76.7	25 OCT 2010
65.2	MAY 2015	71.3A	JUL 2020	76.8	25 OCT 2010
65.3	SEP 2023	71.3B	JUL 2020	79.i	APR 2017
65.4	SEP 2023	71.4	JUL 2020	79.ii	APR 2017
65.5	MAY 2015	71.5	JUL 2020	79.1	APR 2019
65.6	MAY 2015	71.6	JUL 2020	79.2	APR 2019
65.7	MAY 2015	71.7	JUL 2023	79.3	APR 2017
65.8	MAY 2015	71.7A	JUL 2023	79.4	APR 2017
65.9	MAY 2015	71.7B	JUL 2023	79.5	APR 2017
65.10	MAY 2015	71.8	JUL 2023	79.6	APR 2017
65.11	SEP 2012	71.9	JUL 2020	79.7	APR 2017
65.12	SEP 2012	71.10	JUL 2020	79.8	APR 2017
		71.11	APR 2019		
		71.12	APR 2019		
67.i	MAY 2015	71.13	APR 2017	90.i	JUL 2020
67.ii	MAY 2015	71.14	APR 2017	90.ii	JUL 2020
67.1	MAR 2012	71.15	APR 2019	90.1	SEP 2023
67.2	MAR 2012	71.16	APR 2019	90.2	SEP 2023
67.3	25 OCT 2010	71.17	JUL 2020	90.3	JUL 2020
67.4	25 OCT 2010	71.18	JUL 2020	90.4	JUL 2020
67.5	MAR 2026	71.19	JUL 2020	90.5	JUL 2020
67.6	MAR 2026	71.20	JUL 2020	90.6	JUL 2020
67.7	MAR 2026	71.21	APR 2017	90.7	JUL 2020
67.8	MAR 2026	71.22	APR 2017	90.8	JUL 2020
67.9	APR 2017			90.9	JUL 2020
67.10	APR 2017			90.10	JUL 2020
67.11	MAY 2015	75.i	25 OCT 2010	90.11	JUL 2020
67.12	MAY 2015	75.ii	25 OCT 2010	90.12	JUL 2020
67.13	JUL 2020	75.1	25 OCT 2010	90.13	JUL 2020
67.14	JUL 2020	75.2	25 OCT 2010	90.14	JUL 2020
67.15	MAY 2015			90.15	JUL 2020
67.16	MAY 2015	76.i	25 OCT 2010	90.16	JUL 2020
67.17	NOV 2023	76.ii	25 OCT 2010	90.17	JUL 2020
67.18	NOV 2023	76.1	JUL 2023	90.18	JUL 2020
		76.2	JUL 2023	90.19	JUL 2020
71.i	JUL 2020	76.3	MAR 2026	90.20	JUL 2020
71.ii	JUL 2020	76.4	MAR 2026		

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
90.21	JUL 2020			92.34	JUL 2020
90.22	JUL 2020	92.i	JUL 2020	92.35	JUL 2020
90.23	JUL 2020	92.ii	JUL 2020	92.36	JUL 2020
90.24	JUL 2020	92.1	SEP 2023	92.37	JUL 2020
90.25	JUL 2020	92.2	SEP 2023	92.38	JUL 2020
90.26	JUL 2020	92.3	JUL 2020	92.39	JUL 2020
90.27	JUL 2020	92.4	JUL 2020	92.40	JUL 2020
90.28	JUL 2020	92.5	JUL 2020	92.41	JUL 2020
90.29	JUL 2020	92.6	JUL 2020	92.42	JUL 2020
90.30	JUL 2020	92.7	JUL 2020	92.43	JUL 2020
90.31	JUL 2020	92.8	JUL 2020	92.44	JUL 2020
90.32	JUL 2020	92.9	JUL 2020	92.45	JUL 2020
90.33	JUL 2020	92.10	JUL 2020	92.46	JUL 2020
90.34	JUL 2020	92.11	JUL 2020	92.47	JUL 2020
90.35	JUL 2020	92.12	JUL 2020	92.48	JUL 2020
90.36	JUL 2020	92.13	JUL 2020	92.49	JUL 2020
90.37	JUL 2020	92.14	JUL 2020	92.50	JUL 2020
90.38	JUL 2020	92.15	JUL 2020	92.51	JUL 2020
90.39	JUL 2020	92.16	JUL 2020	92.52	JUL 2020
90.40	JUL 2020	92.17	JUL 2020	92.53	JUL 2020
90.41	JUL 2020	92.18	JUL 2020	92.54	JUL 2020
90.42	JUL 2020	92.19	JUL 2020	92.55	JUL 2020
90.43	JUL 2020	92.20	JUL 2020	92.56	JUL 2020
90.44	JUL 2020	92.21	JUL 2020	92.57	JUL 2020
90.45	JUL 2020	92.22	JUL 2020	92.58	JUL 2020
90.46	JUL 2020	92.23	JUL 2020	92.59	JUL 2020
90.47	JUL 2020	92.24	JUL 2020	92.60	JUL 2020
90.48	JUL 2020	92.25	JUL 2020	92.61	JUL 2020
90.49	JUL 2020	92.26	JUL 2020	92.62	JUL 2020
90.50	JUL 2020	92.27	JUL 2020	92.63	JUL 2020
90.51	JUL 2020	92.28	JUL 2020	92.64	JUL 2020
90.52	JUL 2020	92.29	JUL 2020	92.65	JUL 2020
90.53	JUL 2020	92.30	JUL 2020	92.66	JUL 2020
90.54	JUL 2020	92.31	JUL 2020	92.67	JUL 2020
90.55	JUL 2020	92.31A	JUL 2020	92.68	JUL 2020
90.56	JUL 2020	92.31B	JUL 2020		
90.57	JUL 2020	92.32	JUL 2020	95.i	MAR 2026
90.58	JUL 2020	92.33	JUL 2020	95.ii	MAR 2026

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
95.1	APR 2017	96.ii	JUL 2023	97.13	APR 2019
95.2	APR 2017	96.1	APR 2019	97.14	APR 2019
95.3	APR 2017	96.2	APR 2019	97.15	APR 2019
95.4	APR 2017	96.3	APR 2019	97.16	APR 2019
95.5	APR 2017	96.4	APR 2019	97.17	JUL 2020
95.6	APR 2017	96.4A	JUL 2023	97.18	JUL 2020
95.7	APR 2019	96.4B	JUL 2023	97.19	APR 2019
95.8	APR 2019	96.5	JUL 2023	97.20	APR 2019
95.9	APR 2019	96.6	JUL 2023	97.21	APR 2019
95.10	APR 2019	96.7	JUL 2023	97.22	APR 2019
95.11	APR 2017	96.8	JUL 2023	97.23	APR 2019
95.12	APR 2017	96.9	APR 2017	97.24	APR 2019
95.13	APR 2017	96.10	APR 2017	97.25	APR 2019
95.14	APR 2017	96.11	APR 2017	97.26	APR 2019
95.15	APR 2017	96.12	APR 2017	97.27	APR 2019
95.16	APR 2017	96.13	APR 2017	97.28	APR 2019
95.17	APR 2017	96.14	APR 2017	97.29	APR 2019
95.18	APR 2017	96.15	APR 2017	97.30	APR 2019
95.19	APR 2017	96.16	APR 2017		
95.20	APR 2017	96.17	JUL 2023	98.i	MAR 2026
95.21	JUL 2020	96.18	JUL 2023	98.ii	MAR 2026
95.22	JUL 2020	96.19	MAR 2025	98.1	JUL 2023
95.23	MAR 2026	96.20	MAR 2025	98.2	JUL 2023
95.24	MAR 2026			98.2A	JUL 2020
95.25	MAR 2026	97.i	APR 2019	98.2B	JUL 2020
95.26	MAR 2026	97.ii	APR 2019	98.3	APR 2017
95.27	MAR 2026	97.1	APR 2019	98.4	APR 2017
95.27A	MAR 2026	97.2	APR 2019	98.5	APR 2017
95.27B	MAR 2026	97.3	APR 2019	98.6	APR 2017
95.27C	MAR 2026	97.4	APR 2019	98.7	APR 2017
95.27D	MAR 2026	97.5	APR 2019	98.8	APR 2017
95.28	MAR 2026	97.6	APR 2019	98.9	APR 2017
95.29	MAR 2026	97.7	APR 2019	98.10	APR 2017
95.30	MAR 2026	97.8	APR 2019	98.11	APR 2017
95.31	APR 2019	97.9	APR 2019	98.12	APR 2017
95.32	APR 2019	97.10	APR 2019	98.13	MAR 2026
		97.11	APR 2019	98.13A	MAR 2026
96.i	JUL 2023	97.12	APR 2019	98.13B	MAR 2026

REVISION LOG

MAR 2026

<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>	<u>Page</u>	<u>Date</u>
98.14	MAR 2026	98.46	JUL 2020	100.4	MAR 2026
98.15	APR 2019	98.47	JUL 2023	100.5	MAR 2026
98.16	APR 2019	98.48	JUL 2023	100.6	MAR 2026
98.17	APR 2017	98.49	APR 2019	100.7	MAR 2026
98.18	APR 2017	98.50	APR 2019	100.8	MAR 2026
98.19	APR 2017	98.51	APR 2019	100.9	MAR 2026
98.20	APR 2017	98.52	APR 2019	100.10	MAR 2026
98.21	APR 2017	98.53	APR 2019		
98.22	APR 2017	98.54	APR 2019		
98.23	APR 2017	98.55	APR 2019		
98.24	APR 2017	98.56	APR 2019		
98.24A	JUL 2020	98.57	APR 2019		
98.24B	JUL 2020	98.58	APR 2019		
98.24C	JUL 2020	98.59	APR 2019		
98.24D	JUL 2020	98.60	APR 2019		
98.25	APR 2017	98.61	JUL 2020		
98.26	APR 2017	98.62	JUL 2020		
98.27	APR 2017	98.63	MAR 2026		
98.28	APR 2017	98.64	MAR 2026		
98.29	APR 2017				
98.30	APR 2017	99.i	APR 2017		
98.31	APR 2017	99.ii	APR 2017		
98.32	APR 2017	99.1	MAR 2026		
98.33	APR 2017	99.2	MAR 2026		
98.34	APR 2017	99.3	JUL 2023		
98.35	APR 2017	99.4	JUL 2023		
98.36	APR 2017	99.5	MAR 2025		
98.37	APR 2017	99.6	MAR 2025		
98.38	APR 2017	99.7	JUL 2023		
98.39	APR 2017	99.8	JUL 2023		
98.40	APR 2017	99.9	JUL 2023		
98.41	APR 2017	99.10	JUL 2023		
98.42	APR 2017				
98.43	APR 2017	100.i	MAY 2021		
98.44	APR 2017	100.ii	MAY 2021		
98.45	JUL 2020	100.1	MAR 2026		
98.45A	JUL 2020	100.2	MAR 2026		
98.45B	JUL 2020	100.3	MAR 2026		