

Page 1 of 1

R22 SERVICE LETTER SL-99

DATE: 1 August 2025

TO: R22-series Owners, Operators, and Maintenance Personnel

SUBJECT: RHC Part Number A257-25 Lubricant Usage

PARTS AFFECTED: A005-7 & A005-14 main rotor blade & spindle assemblies.

BACKGROUND: A257-25 lubricant is General Motors-approved Dexron VI or Dexron-VI ATF (automatic transmission fluid), and is approved by RHC for use in specified R22 main rotor blade & spindle assemblies.

COMPLIANCE PROCEDURE:

At operator's discretion, install A257-25 lubricant in place of A257-4 lubricant in A005-7 or A005-14 main rotor blade & spindle assemblies.

Do not intermix lubricants. If previously installed oil type is unknown, completely drain old lubricant before servicing with new lubricant.